

Report ID:	27,818,048	Version:	3
Created:	19 Dec 2025		

	Hyundai	Model:	Tucson
Body Style:	SUV	Year:	2023
Rego No.:	QHH865	Rego Expiry:	27 Nov 2026
WoF Expiry:	22 Sep 2026	Odometer:	13,150 Kms
Good No.:	27818048	VIN:	TMAJC811MPJ176131
Next Service:	18349km / 14/06/2025	Service History:	Yes
liagnostic testing un ull mechanical inspe (ey	only. Consideration is made dertaken. The vehicle has be ection prior to purchase and the second of	een driven up to 50km/l d this can be arranged f	ls W = Significant scuffs
SC 6		* *	
sc			
J			1 1
lote: some defects Body Inspection	and blemishes may not be	displayed in the diagra	m
		displayed in the diagra	m
Body Inspection Conditions Dur	on Comments		Dry
Body Inspection Conditions Dur Under Carriag	on Comments		Dry
Body Inspection Conditions Dur	ing Body Inspection e and Under Bonnet		Dry
Conditions Dur Under Carriag	ing Body Inspection e and Under Bonnet		Dry
Conditions Dur Under Carriag FWD	ing Body Inspection e and Under Bonnet		Dry
Conditions Dur Under Carriag FWD Interior Comm	ing Body Inspection e and Under Bonnet nents Good		Dry
Conditions Dur Under Carriag FWD Interior Comm Seats: Carpets:	ing Body Inspection e and Under Bonnet nents Good Good		Dry
Conditions Dur Under Carriag FWD Interior Comm Seats: Carpets: Panels:	ing Body Inspection e and Under Bonnet ments Good Good Good Good		Dry
Conditions Dur Under Carriag FWD Interior Comm Seats: Carpets: Panels: Dashboard: General Comm Windscreen stor	ing Body Inspection e and Under Bonnet ments Good Good Good Good Good nents ne chip - has been rep	Inspection Comm	Dry
Conditions Dur Under Carriag FWD Interior Comm Seats: Carpets: Panels: Dashboard: General Comm Windscreen stor	ing Body Inspection e and Under Bonnet nents Good Good Good Good nents ne chip - has been reposed by the chip - has been re	Inspection Comm	Dry
Conditions Dur Under Carriag FWD Interior Comm Seats: Carpets: Panels: Dashboard: General Comm Windscreen stor Road Condition Engine Timing	ing Body Inspection e and Under Bonnet ments Good Good Good Good nents ne chip - has been repose buring Test Drive Mechanism	Dry Unknown	Dry
Conditions Dur Under Carriag FWD Interior Comm Seats: Carpets: Panels: Dashboard: General Comm Windscreen stor Road Condition Engine Timing Evidence of Car	ing Body Inspection e and Under Bonnet nents Good Good Good Good heents he chip - has been reported by the chip - has been re	Dry Unknown Yes	Dry
Conditions Dur Under Carriag FWD Interior Comm Seats: Carpets: Panels: Dashboard: General Comm Windscreen stor Road Condition Engine Timing	ing Body Inspection e and Under Bonnet ments Good Good Good Good nents ne chip - has been repose buring Test Drive Mechanism	Dry Unknown Yes	Dry

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	~		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	•
Left front			5.5 mm
Right front			5.5 mm
Left rear		(6.0 mm
Right rear		(6.0 mm
Spare	N/A		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	1		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	V		
Window winder RL	/		
Window winder RR	1		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			~
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	/		
-			

I have read and understood this condition guide:

NAME _

SIGNATURE