

Report ID:	27,818,478	Version:	2
Created:	19 Dec 2025		


Requires

Make:	Holden	Model:	Barina
Body Style:	Hatchback	Year:	2015
Rego No.:	JBU611	Rego Expiry:	29 Apr 2026
WoF Expiry:	02 Jan 2027	Odometer:	40,852 Kms
Good No.:	27818478	VIN:	KL3TA4889FB046424
Next Service:	51000	Service History:	No

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Interior Comm	nents
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good
General Comments	

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No	Kms
Inspected by:	Melissa Wilson		
Published by:	Melissa Wilson		
Inspection Date:	19 Dec 2025		

I have read	and	unc	lers	tood
this conditi	ion c	uide	2:	

NAME			

	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	V V		
Noise	✓		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation			
Noise			
Clutch			_
CV joints			
Wheel bearings	_		
Brakes	•		
Performance			
Hand brake	· /		
Tyres (lowest observed tread de	onth of	turos)	
Left front	еритог	Lyles)	6 mm
Right front			6 mm
Left rear			4 mm
Right rear			5 mm
Spare	Yes		
Suspension		Ī	
Suspension performance	V		
Steering performance			
Shock absorbers			
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	~		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			~
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			-
Reversing camera			
J			

SIGNATURE		