

Basic Condition Guide

Report ID:	27,820,131	Version:	1
Created:	02 Dec 2025		

		ОК	Requires Attention	N/A
	Engine			
026 Kms	Oil level			
0706101005	Smoke & fumes	/		
0706101005	Engine performance	/		
	Noise	/		
een dismantled or	Coolant condition	/		
e Vendor recommends a Il charge.	Cooling performance	/		
	Radiator / Hoses (visual)	/		
<i>N</i> = Significant scuffs	Transmission	_		
	Operation	/		
	Noise	/		
	Clutch			~
s sc	CV joints	/		
	Wheel bearings	/		
HII	Brakes			
sc	Performance	/		
30	Hand brake	/		
7114	Tyres (lowest observed tread	depth of	tyres)	
	Left front		2	2.8 mm
SPT	Right front		3	3.0 mm
	Left rear		4	1.1 mm
	Right rear		6	6.2 mm
	Spare	Yes		
	Suspension			
	Suspension performance	/		
	Steering performance	/		
	Shock absorbers	/		
	Air Conditioning / Heater	•	•	
	Operation	/		
	Electrical / Accessories			
			· ·	
	Electrical / Accessories	V	V	
	Electrical / Accessories Head lights	V	<i>V</i>	
	Electrical / Accessories Head lights Tail lights	-	<i>V</i>	
	Electrical / Accessories Head lights Tail lights Indicators	/	V	
	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights	V	V	
	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear)	V V	V	
	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL	\(\tau \)	V	
	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR	\(\frac{1}{V} \)		
	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL	\(\text{\tinx{\text{\tex{\tex		
	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	V V V V V V V V V V V V V V V V V V V		
	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	V V V V V V V V		
	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V V V V V V V V V V V V V V V V V		V
Kms	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	V V V V V V V V		
Kms	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\frac{1}{2} \) \(\frac{1} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1} \) \(\frac{1} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(<i>V</i>
Kms	Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	\(\frac{1}{2} \) \(\frac{1} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1} \) \(\frac{1} \) \(\frac{1}{2} \) \(\frac{1}{2} \) \(V

WoF Expiry: 04 May 2026 Odometer: 20 Good No.: 27820131 VIN: 7A Next Service: 112457 Service History: No Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts his report is a guide only. Consideration is made for age and mileage. Parts his report is a guide only. Consideration is made for age and mileage. Parts his report is a guide only. Consideration is made for age and mileage. Parts his report is a guide only. Consideration is made for age and mileage. Parts his report is a guide only. Consideration is made for age and mileage. Parts his report is a guide only. Consideration is made for age and mileage. Parts his report is a guide only. Consideration is made for age and this can be arranged for an acceptance of the service of t	Aug 2026 3,295 Kms 8H6070706101005 Eve not been dismantled or cold. The Vendor recommends a additional charge.
WoF Expiry: 04 May 2026 Odometer: 20 Good No.: 27820131 VIN: 7A Next Service: 112457 Service History: No Note: This report is a quide only. Consideration is made for age and mileage. Parts his diagnostic testing undertaken. The vehicle has been driven up to 50km/h fror ull mechanical inspection prior to purchase and this can be arranged for an over the properties of the	8,295 Kms 8H6070706101005 eve not been dismantled or a cold. The Vendor recommends a additional charge.
Good No.: 27820131 VIN: 7.A Next Service: 112457 Service History: No Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts h diagnostic testing undertaken. The vehicle has been driven up to 50km/h for ull mechanical inspection prior to purchase and this can be arranged for an Key Se Scratch Re Rust Ce Crack *= Decals Dent PT = Paint defect P = Pin dent SC = Stone Co SSC SSC SDSC SSC SDSC SSC SDSC SSC SDSC SSC SDSC Conditions During Body Inspection Under Carriage and Under Bonnet Inspection Comment Front wheel drive Oil leak Transmission leak Interior Comments Seats: Good Carpets: Good Carpets: Good Carpets: Good	8H6070706101005 Ive not been dismantled or cold. The Vendor recommends a
Next Service: 112457 Note: This report is not a warranty lifis report is a guide only. Consideration is made for age and mileage. Parts he liagnostic testing undertaken. The vehicle has been driven up to 50km/h fror ull mechanical inspection prior to purchase and this can be arranged for an example of the properties	ive not been dismantled or i cold. The Vendor recommends a additional charge.
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts h diagnostic testing undertaken. The vehicle has been driven up to 50km/h fror ull mechanical inspection prior to purchase and this can be arranged for an Key S = Scratch R = Rust C = Crack * = Decals D = Dent PT = Paint defect P = Pin dent SC = Stone C S SC S D SC Oute: some defects and blemishes may not be displayed in the diagram Body Inspection Comments Minor stonechips on windscreen Conditions During Body Inspection Under Carriage and Under Bonnet Inspection Comment Front wheel drive Oil leak Transmission leak Interior Comments Seats: Good Carpets: Good	cold. The Vendor recommends a additional charge.
This report is a guide only. Consideration is made for age and mileage. Parts his apport is a guide only. Consideration is made for age and mileage. Parts his diagnostic testing undertaken. The vehicle has been driven up to 50km/h fror under mechanical inspection prior to purchase and this can be arranged for an executive of the control of the contr	cold. The Vendor recommends a additional charge.
S = Scratch R = Rust C = Crack * = Decals D = Dent PT = Paint defect P = Pin dent SC = Stone C S SC S D SC	W - Significant co.ff
S SC S D SC S D SC S D SC S S D S	\// = Cigniticant cart
S SC S D SC S S SC S D SC S S S S S S D SC S S S S S D SC S S S S S D SC S S D SC S S D S S S D S C S D S S S D S C S D S	•
S SC Solution Some defects and blemishes may not be displayed in the diagram Body Inspection Comments Minor stonechips on windscreen Conditions During Body Inspection Under Carriage and Under Bonnet Inspection Comment Front wheel drive Oil leak Transmission leak Interior Comments Seats: Good Carpets: Good	iiba
Scats: Good Carpets: Good Carpets: Good Carpets: Good Carpets: Conditions During Body Inspection Conditions During Body Inspection Draw Under Carriage and Under Bonnet Inspection Comment Front wheel drive Oil leak Carpets: Good Carpets: Good	
Under Carriage and Under Bonnet Inspection Comment Front wheel drive Oil leak Transmission leak Interior Comments Seats: Good Carpets: Good	SC SC S PT S
Front wheel drive Oil leak Transmission leak Interior Comments Seats: Good Carpets: Good	
Oil leak Transmission leak Interior Comments Seats: Good Carpets: Good	
Seats: Good Carpets: Good	
Carpets: Good	
•	
Panels: Good	
Dashboard: Good	
General Comments	
Due for service	
Right fog light not working	

Evidence of Can	n Belt Replacement	Yes	No	Kı
Inspected by:	Cameron Senior-Arn	old		
Published by:	Janine Bell			
Inspection Date:	28 Nov 2025			
nave read and III	aderstood			

Timing Chain

this condition guide:

Engine Timing Mechanism

	AME	NΙΛ