

Basic Condition Guide

•	Report ID:	27,820,154	Version:	1
	Created:	04 Dec 2025		

U	ntuet	S Bas	Created: 04 Dec 2025					
Make:	Chrysler	Model:	Dodge		ОК	Requires Attention	N/A	
Body Style:	Wagon	Year:	2008	Engine	UK	Attention	IN/A	
Rego No.:	KMS51	Rego Expiry:	01 Jan 2026	Oil level	V	<u> </u>		
WoF Expiry:	14 Oct 2026	Odometer:	201,067 Kms	Smoke & fumes	1			
Good No.:	27820154	VIN:	1D8G958K68W125778	Engine performance	1			
Next Service:	No record	Service History:	No	Noise	1			
lote: This report is	not a warranty	-	Coolant condition	+				
iagnostic testing ur	e only. Consideration is madendertaken. The vehicle has b	een driven up to 50km/	Cooling performance					
ıll mechanical insp	ection prior to purchase an	d this can be arranged	Radiator / Hoses (visual)					
(ey	D	`	Transmission					
	= Rust $C = C$ T = Paint defect $P = P$		als W = Significant scuffs one Chips	Operation	V			
			WS	Noise	1			
SD		SPS	Clutch			·		
				CV joints	V			
	$(0)_{\mathbb{F}}$			Wheel bearings	V			
D PT W				Brakes		<u> </u>		
M	19/1			Performance	V			
] -	PT	Hand brake	1			
	10			Tyres (lowest observed tread depth of tyres)				
			Left front	6.0 mm				
			Right front	7.5 mm				
			Left rear	5.0 mm				
S	W		Right rear	5.0 mm				
lote: some defects	and blemishes may not be	e displayed in the diagr	am	Spare	Yes			
	on Comments	alsplayed in the diagr		Suspension				
		or mirror fitting is br	oken. Right door mirror glass is	Suspension performance	V			
	-		aking on front bumper. Rear	Steering performance	V			
wiper needs ne Stone cracks o	w blade. Tools are mi n windshield.	issing(only Jack in	boot).	Shock absorbers	V			
	ring Body Inspection		Air Conditioning / Heater					
	ge and Under Bonnet	Inspection Comn	Operation		·			
	ngine and transmissio		Electrical / Accessories					
				Head lights	V			
				Tail lights	V			
Interior Comn	nents			Indicators		V		
Seats:	Good			Dashboard warning lights	1			
Carpets:	Good	-		Wipers (front & rear)	/			
Panels:	Good	Window winder FL	/					
Dashboard:	Good		Window winder FR	1				
General Comr			Window winder RL		~			
•	aulty. Left rear power		Window winder RR	/				
	witch is not fitted corre is not operating. Rad	•	Rear view mirrors		~			
	is not operating. Rad off. Right rear door loo		Radio (basic test only)	/				
	ns During Test Drive	Dry	CD (basic test only)			1		
Engine Timing		Timing Chain		Number of keys	1	1		
		t		•		1		

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 01 Dec 2025

Yuki Itohara

Glen Charlton

NAME ____

No

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Yes

SIGNATURE

1

1