


| Report ID: | 27,820,787  | Version: | 1 |
|------------|-------------|----------|---|
| Created:   | 03 Dec 2025 |          |   |

| Ford        | Model:                                   | Territory   |
|-------------|--|---|
| SUV         | Year:                                    | 2013  |
| GUQ260      | Rego Expiry:                             | 28 Mar 2026   |
| 12 Dec 2026 | Odometer:                                | 186,134 Kms   |
| 27820787    | VIN:                                     | 6FPAAAJGATDM27533   |
| 194,000 Kms | Service History:                         | No  |
|             | SUV<br>GUQ260<br>12 Dec 2026<br>27820787 | SUV Year:   GUQ260 Rego Expiry:   12 Dec 2026 Odometer:   27820787 VIN: |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### **Body Inspection Comments**

| Conditions During Body Inspection                   | Dry |  |  |  |
|---|-----|--|--|--|
| Under Carriage and Under Bonnet Inspection Comments |     |  |  |  |

# **Interior Comments**

4WD

| Seats:     | Stains. Slight wear on drivers seat               |  |  |
|------------|---|--|--|
| Carpets:   | Wear on drivers side                              |  |  |
| Panels:    | Wear on F/R door handle and mark on F/L door card |  |  |
| Dashboard: | Good  |  |  |

## **General Comments**

| Road Conditions During Test Drive |                  | Dry          |    |             |
|-----------------------------------|------------------|--------------|----|-------------|
| Engine Timing Mechanism           |                  | Cambelt      |    |             |
| Evidence of Cam Belt Replacement  |                  | <b>✓</b> Yes | No | 181,700 Kms |
| Inspected by:                     | Hoani Saunders   |              |    |             |
| Published by:                     | Jayson Rodriguez | Z            |    |             |
| Inspection Date:                  | 02 Dec 2025      |              | ·  |             |

| I have read    | and  | understood |
|----------------|------|------------|
| thic condition | on a | uido       |

| NAME |  |  |  |
|------|--|--|--|

|                                | ОК         | Requires<br>Attention | N/A    |
|--------------------------------|------------|-----------------------|--------|
| Engine                         |            |                       |        |
| Oil level                      | ~          |                       |        |
| Smoke & fumes                  | ~          |                       |        |
| Engine performance             | V          |                       |        |
| Noise                          | 1          |                       |        |
| Coolant condition              | \( \tau \) |                       |        |
| Cooling performance            | ~          |                       |        |
| Radiator / Hoses (visual)      | 1          |                       |        |
| Transmission                   |            |                       |        |
| Operation                      | ~          |                       |        |
| Noise                          | 1          |                       |        |
| Clutch                         |            |                       | ~      |
| CV joints                      | 1          |                       |        |
| Wheel bearings                 | 1          |                       |        |
| Brakes                         | ı          |                       |        |
| Performance                    | <b>/</b>   |                       |        |
| Hand brake                     | 1          |                       |        |
| Tyres (lowest observed tread d | epth of    | tyres)                |        |
| Left front                     |            |                       | 6.4 mm |
| Right front                    |            | (                     | 6.1 mm |
| Left rear                      |            | (                     | 6.4 mm |
| Right rear                     |            | (                     | 5.3 mm |
| Spare                          | Yes        |                       |        |
| Suspension                     |            |                       |        |
| Suspension performance         | V          |                       |        |
| Steering performance           | 1          |                       |        |
| Shock absorbers                | 1          |                       |        |
| Air Conditioning / Heater      | l.         |                       |        |
| Operation                      | <b>/</b>   |                       |        |
| Electrical / Accessories       |            |                       |        |
| Head lights                    | <b>/</b>   |                       |        |
| Tail lights                    | 1          |                       |        |
| Indicators                     | 1          |                       |        |
| Dashboard warning lights       | V          |                       |        |
| Wipers (front & rear)          | 1          |                       |        |
| Window winder FL               | •          |                       |        |
| Window winder FR               | V          |                       |        |
| Window winder RL               | 1          |                       |        |
| Window winder RR               | 1          |                       |        |
| Rear view mirrors              | 1          |                       |        |
| Radio (basic test only)        | 1          |                       |        |
| CD (basic test only)           | 1          |                       |        |
| Number of keys                 | 1          | •                     |        |
| Central locking                | 1          |                       |        |
| Remote locking                 | 1          |                       |        |
| Sat. nav. (basic test only)    |            |                       | 1      |
| Reversing camera               | 1          |                       |        |
|                                |            |                       |        |