

Report ID:	27,821,819	Version:	3	
Created:	12 Dec 2025			

1

1

1 1

1

•

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking

		Dooi	a Candition Cuida	ricport ib.	21,021,019	VCI	31011.	
	nuel	S Dasi	c Condition Guide	Created:	12 Dec 2025			
Make: Fiat Mod		Model:	del: Punto				Requires	NI/A
Body Style: Hatchback		Year: 2016		Engine		OK	Attention	N/A
Rego No.: JNP403		Rego Expiry:	28 Jun 2026			V		
WoF Expiry: 24 Dec 2026		Odometer:	89,972 Kms	Smoke & fumes		1		
Good No.: 27821819		VIN: ZFA19900000981274				V		
		Service History:	Yes	Engine performance		1		
Note: This report is r	not a warranty			Noise Coolant co	adition	1		
This report is a guide of	only. Consideration is made dertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/h	orts have not been dismantled or a from cold. The Vendor recommends a			1		
ull mechanical inspe	ction prior to purchase an	d this can be arranged f	or an additional charge.	Cooling pe		1		
Кеу					loses (visual)			
	= Rust $C = C$			Transmission				<u> </u>
D = Dent PT	= Paint defect $P = P$	in dent SC = Stor	ne Chips	Operation		- 1		
	S	P	D	Noise		/		
				Clutch				•
	\sim		S	CV joints		/		
$\overline{}$				Wheel bea	rings	/		
$-\!$	8		1	Brakes				
11	M = M	11 1		Performan	ce	/		
				Hand brake	2	/		
				Tyres (lowe	est observed tread o	lepth of	tyres)	
				Left front			3	3.0 mm
				Right front			3	3.0 mm
				Left rear		6.0 mi		6.0 mm
D	<u>s</u>			Right rear			6	6.0 mm
Note: some defects a	and blemishes may not be	displayed in the diagra	m	Spare		Yes		
Body Inspection	on Comments			Suspensio	n			
				Suspension	performance	'		
				Steering pe	erformance	'		
				Shock abso	rbers	/		
Conditions During Body Inspection Dry					ioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
				Electrical /	Accessories			
				Head lights	;	/		
				Tail lights		1		
Interior Comm	ents			Indicators		1		
Seats: Good				Dashboard	warning lights	1		
Carpets: Good				Wipers (fro		1		
Panels: Good				Window w		1		
Dashboard: Good				Window w		1		
	1					ar i		

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Cambelt		
Evidence of Car	n Belt Replacement	Yes	V No	Kms
Inspected by:	Eleoit Kumar			
Published by:	Sam Huang			
Inspection Date:	04 Dec 2025			

General Comments

I have read and understood		
this condition guide:	NAME	SIGNATURE