

•	Report ID:	27,822,535	Version:	3
	Created:	12 Dec 2025		

N/A

5.5 mm 4.5 mm 4.0 mm 3.5 mm

		Posi	a Candition Cuida	Report ID:	27,822,535	Ve	rsion:	3
	urner	S Dasi	c Condition Guide	Created:	12 Dec 2025			
Make:	Ford	Model:	Courier				Requ	
Body Style:	Utility	Year:	2006	Engino		OK	Atten	tion
Rego No.:	DHK657	Rego Expiry:	30 May 2026	Engine Oil level		V		
WoF Expiry:	11 Nov 2026	Odometer:	384,627 Kms	Smoke & fu	ımas	V		\dashv
Good No.:	27822535	VIN:	MNABSFE406W506247			V		
Next Service:	386,800kms	Service History:	No	Engine per Noise	Torritance	V		
Note: This report is not a warranty					ndition	-		
			arts have not been dismantled or a from cold. The Vendor recommends a			· ·		
full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling performance Radiator / Hoses (visual)			
Key				Transmiss	. ,	/		
	R = Rust C = C PT = Paint defect P = P			Operation	ion	· ·	l	T
— Delit i		5C = 3tol	ie Cilips	Noise		1		
D		PT P	PT D	Clutch		1		
				CV joints		· ·		
	$\mathcal{O}_{\mathcal{F}}$		S D		rings	1		
SC /		· · · ·)		Wheel bearings Brakes				
MACHINA					 ce	· /	Π	Т
			D	Hand brake		1		
SC SDRP				Tyres (lowest observed tread depth of tyres)				
							5.	
				Right front				4.
				Left rear				4.
P D PT P PT PT P				Right rear				3.
Note: some defect	s and blemishes may not be	e displayed in the diagra	m	Spare		Yes		
	tion Comments			Suspensio	n			
				Suspension	n performance	V		
				Steering pe	erformance	1		
				Shock abso	orbers	1		
Conditions During Body Inspection Dry				Air Condit	ioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation		V		Π
Sills dented.				Electrical /	Accessories			
				Head lights	5	1		T
				Tail lights		1		
Interior Com	ments			Indicators		/		
Seats:	Good			Dashboard	warning lights	~		
Carpets:	Good			Wipers (fro	nt & rear)	~		
Panels:	Good			Window w	inder FL	1		
Dashboard:	Good			Window w	inder FR	~		
			,				1	-

Road Condition	s During Test Drive	Dry		
Engine Timing N	Леchanism	Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	310,000 Kms
Inspected by:	LukaAjitvan Woer	den		
Published by:	Harry Dodds			
Inspection Date:	29 Nov 2025			

I have read an	d understood		
this condition	guide:	NAME	

General Comments

SIGNATURE			

1

1

1 1

1

Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking