


Basic Condition Guide

| Report ID: | 27,822,629 | Version: | 1 |
|------------|-------------|----------|---|
| Created: | 02 Dec 2025 | | |

| Make: | Nissan | Model: | Tiida | | |
|---|-------------|------------------|-------------------|--|--|
| Body Style: | Hatchback | Year: | 2008 | | |
| Rego No.: | MHC484 | Rego Expiry: | 27 Jan 2026 | | |
| WoF Expiry: | 15 Dec 2026 | Odometer: | 95,415 Kms | | |
| Good No.: 27822629 VIN: | | VIN: | 7AT0DH78X19208185 | | |
| Next Service: | 100,000Kms | Service History: | No | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | |

Key

S = Scratch* = DecalsW = Significant scuffs R = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

| Conditions During Body Inspection | Dry | | | |
|---|-----|--|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | | |

| Interior Comments | |
|-------------------|---------|
| Seats: | Average |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Average |
| General Comments | |

AC not working.

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|-------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Bobby Zhong | |
| Published by: | Bobby Zhong | |
| Inspection Date: | 02 Dec 2025 | |

| have read and understood | | | |
|--------------------------|------|--|--|
| his condition quide: | NAME | | |

| | ОК | Requires Attention | N/A |
|--------------------------------|-------------------|-----------------------|----------|
| Engine | | | |
| Oil level | / | | |
| Smoke & fumes | / | | |
| Engine performance | / | | |
| Noise | / | | |
| Coolant condition | V V | | |
| Cooling performance | / | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | ~ |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | / | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | | 6 mm |
| Right front | | | 6 mm |
| Left rear | | | 6 mm |
| Right rear | | | 6 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | | ✓ | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | / | | |
| Indicators | ✓ | | |
| Dashboard warning lights | \(\frac{1}{2} \) | | |
| Wipers (front & rear) | | | |
| Window winder FL | / | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | / | | |
| Rear view mirrors | / | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | | | ~ |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | | | V |
| Reversing camera | | | ' |
| | | | |

| SIGNATURE | | |
|-----------|--|--|