

•	Report ID:	27,822,714	Version:	1
	Created:	29 Nov 2025		

mm mm mm mm

		Pooi	a Canditian Cuida	Report ID:	21,022,114	ve	rsion:		
	ntuet	S Dasi	c Condition Guide	Created:	29 Nov 2025				
Make:	BYD	Model:	Dolphin				Requires		
Body Style: Hatchback		Year:	2023			OK	Attention	N/	
Rego No.: QGF248		Rego Expiry:	30 Oct 2026	Oil level		<u> </u>			
WoF Expiry:	31 Oct 2026	Odometer:	15,411 Kms	Smoke & fu	ımos			-	
Good No.:	27822714	VIN:	LC0CE4CC4P0401465			1		<u>-</u>	
Next Service:	31000	Service History:	No	Engine per	Torriance	<i>'</i>			
Note: This report is	not a warranty			Noise	n dition	1		_	
This report is a guide	e only. Consideration is mad	e for age and mileage. Pa	arts have not been dismantled or n from cold. The Vendor recommends a	Coolant condition Cooling performance					
	ection prior to purchase an					1			
Key					Hoses (visual)				
	C = Rust $C = C$			Transmissi	lon		I		
D = Dent P	T = Paint defect P = P	in dent $SC = Sto$	ne Chips	Operation		/		_	
		SP P		Noise		/			
				Clutch				<u>ر</u>	
	(0)=		P	CV joints		/		-	
		<u> </u>		Wheel bearings					
7				Brakes					
\mathcal{H}				Performan		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
					Turia braice				
D				Tyres (lowest observed tread depth of tyres)					
					Left front		2 r		
				Right front					
DW	W I	D W SC		Left rear				4 r	
				Right rear				4 r	
	and blemishes may not be	displayed in the diagra	im 	Spare		N/A			
Body Inspect	ion Comments			Suspensio			I		
				-	n performance	/			
					erformance	/			
			T_	Shock abso		/			
	ring Body Inspection		Dry		ioning / Heater		I		
Under Carriag	ge and Under Bonnet	Inspection Comm	nents	Operation		/			
					Accessories		T	1	
				Head lights	;	/			
				Tail lights		/			
Interior Comr				Indicators		/		_	
Seats:	Good				l warning lights		/		
Carpets:	Good	-		Wipers (fro		/			
Panels:	Good			Window wi		/			
Dashboard:	Good			Window wi		/			
General Com				Window wi		/		<u> </u>	
	warning displayed commercial charging o	cable		Window wi	inder RR	/		<u> </u>	

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Unknown		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Sione Mae			
Published by:	Sione Mae			
Inspection Date:	29 Nov 2025			

I have read and understood this condition guide:

Equipped with commercial charging cable

NAME			

SIGNATURE			

1

1

1 1

1

1

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera