

-	Report ID:	27,823,011	Version:	2
	Created:	12 Dec 2025		

Basic Condition Guide			Report ID. 21,823,011 Version. 2						
	Dille	<u> </u>		Created:	12 Dec 2025				
Make:	Honda	Model:	Jazz				Requires		
Body Style:	Hatchback	Year:	2012	Engine		OK	Attention	N/A	
Rego No.:	GHK561	Rego Expiry:	29 Jul 2026			V			
WoF Expiry:	22 Dec 2026	Odometer:	167,284 Kms	Oil level Smoke & fumes		<b>V</b>			
Good No.:	27823011	VIN:	JHMGE6750CS206542	Engine performance		V			
Next Service:	177, 306 Kms	Service History:	Yes	Noise		<b>V</b>	+ +		
Note: This report is	not a warranty			Coolant condition		<b>V</b>			
diagnostic testing ur	only. Consideration is made for age and mileage. Parts have not been dismantled or ndertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a			Cooling performance		<b>V</b>			
full mechanical inspection prior to purchase ar		d this can be arranged for an additional charge.		Radiator / Hoses (visual)		<b>V</b>			
Кеу				Transmission					
	= Rust $C = C$ T = Paint defect $P = P$		3		1011	<b>V</b>			
		5C = 3tol	ie Chips	Operation Noise		<b>V</b>			
( sc )(	<u>s</u>	D P		Clutch		<b>V</b>			
				CV joints		·			
SD				Wheel bea	rings	1			
W	W				Brakes				
SC			Performan	ce	·				
				Hand brake		1			
			Tyres (lowest observed tread depth of tyres)						
				Left front				I.0 mn	
				Right front		5.0 mi			
				Left rear		5.0 m			
S W S W			Right rear		5.0		5.0 mn		
Note: some defects and blemishes may not be displayed in the diagram				Spare		Yes			
	on Comments			Suspension					
Stone chips have	ve been repaired.			Suspension	n performance	V			
				Steering pe	erformance	1			
				Shock abso	orbers	1			
Conditions During Body Inspection Dry Under Carriage and Under Bonnet Inspection Comments				Air Conditioning / Heater					
				Operation 🗸					
				Electrical /	'Accessories				
			Head lights	5	•				
				Tail lights		1			
Interior Comments				Indicators		1			
Seats:	eats: Average			Dashboard	l warning lights	1			
-					<u> </u>				

Interior Comments			
Seats:	Average		
Carpets:	Average		
Panels:	Good		
Dashboard:	Good		
General Comn	General Comments		

## Front Wheel Drive.

Road Condition	s During Test Drive	Dry
Engine Timing N	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Haden Brown	
Published by:	Shanna Bullion	
Inspection Date:	01 Dec 2025	

SIGNATURE			

1

1

1

1

1 2

1

1

Wipers (front & rear)

Window winder FL Window winder FR Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

I have read and understood
this condition guide: