

| • | Report ID: | 27,823,146 | Version: | 2 |
|---|------------|-------------|----------|---|
| | Created: | 16 Dec 2025 | | |


| | | ОК | Requires Attention | N/A |
|--------|-----------------------------------|---------------------------------------|-----------------------|--------|
| | Engine | | | |
| | Oil level | / | | |
| | Smoke & fumes | / | | |
|)7 | Engine performance | 1 | | |
| | Noise | 1 | | |
| | Coolant condition | 1 | | |
| ends a | Cooling performance | 1 | | |
| | Radiator / Hoses (visual) | 1 | | |
| scuffs | Transmission | | | |
| 5005 | Operation | / | | |
| | Noise | 1 | | |
| C | Clutch | | | 1 |
| D | CV joints | V | | |
| ט | Wheel bearings | 1 | | |
| | Brakes | | | |
| | Performance | · | | |
| c | Hand brake | 1 | | |
| | Tyres (lowest observed tread | depth of | tvres) | |
| | Left front | | | 1.0 mm |
| | Right front | | | 1.5 mm |
| | Left rear | | | 1.0 mm |
| SC | Right rear | | | 1.5 mm |
| | Spare | Yes | | |
| | Suspension | | | |
| | Suspension performance | V | | |
| | Steering performance | 1 | | |
| | Shock absorbers | 1 | | |
| | Air Conditioning / Heater | | | |
| | Operation | | | |
| | Electrical / Accessories | | | |
| | Head lights | · / | | |
| | Tail lights | 1 | | |
| | Indicators | 1 | | |
| | Dashboard warning lights | 1 | | |
| | Wipers (front & rear) | · / | | |
| | Window winder FL | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| | Window winder FR | V | | |
| | Window winder RL | 1 | | |
| | Window winder RR Window winder RR | 1 | | |
| | | V | | |
| | Rear view mirrors | V | | |
| | Radio (basic test only) | V | | |
| | CD (basic test only) | - | | L |
| | Number of keys | 1 | 1 | Ι |
| Kms | Central locking | / | | |
| | Remote locking | / | | |
| | Sat. nav. (basic test only) | | | |
| | Reversing camera | | | |

| Make: | Nissan | Model: | Navara |
|---------------|-------------|------------------|-------------------|
| Body Style: | Utility | Year: | 2015 |
| Rego No.: | JAT598 | Rego Expiry: | 31 May 2026 |
| WoF Expiry: | 04 Nov 2026 | Odometer: | 120,714 Kms |
| Good No.: | 27823146 | VIN: | VSKCVND40A0563007 |
| Next Service: | 128,600 Kms | Service History: | No |

Inis report is a guide only. Consideration is made for age and mileage. Parts have not been dismantied or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recomme full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Lock nut key with spare wheel tools.

| Conditions During Body Inspection | Dry |
|---|------|
| Under Carriage and Under Bonnet Inspection Comm | ents |

| Interior Comments | | | |
|-------------------|--|--|--|
| Seats: | Good, minor tear in drivers seat base. | | |
| Carpets: | Good, missing rear floor mats. | | |
| Panels: | Good | | |
| Dashboard: | Good, steering wheel wearing. | | |
| | | | |

General Comments

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|----------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Troy Smith | |
| Published by: | Shanna Bullion | |
| Inspection Date: | 30 Nov 2025 | |

| l have | read | and | under | stood |
|---------|-------|------|-------|-------|
| thic co | nditi | on a | uida | |

| NAME | | | |
|------|--|--|--|