

Basic Condition Guide

Report ID:	27,823,263	Version:	1
Created:	04 Dec 2025		

		OK	Requires Attention	N/A
	Engine	OIL	Accellation	14//
	Oil level	V		
	Smoke & fumes	1		
)	Engine performance	1		
	Noise		~	
	Coolant condition	V		
nds a	Cooling performance	1		
	Radiator / Hoses (visual)	1		
scuffs	Transmission			
,cuiis	Operation	/		
214	Noise	1		
R W	Clutch			1
D	CV joints	1		
	Wheel bearings	/		
	Brakes		•	
	Performance	'		
sc	Hand brake	1		
	Tyres (lowest observed tread	depth of	tyres)	
	Left front		4	4.0 mm
5	Right front		ţ	5.5 mm
	Left rear		ţ	5.0 mm
<u> </u>	Right rear		ţ	5.0 mm
	Spare	Yes		
	Suspension			
	Suspension performance	/		
	Steering performance	'		
	Shock absorbers	/		
	Air Conditioning / Heater			
	Operation	/		
	Electrical / Accessories			
	Head lights	/		
	Tail lights	/		
	Indicators	/		
	Dashboard warning lights	/		
	Wipers (front & rear)	•		
	Window winder FL	•		
	Window winder FR	/		
	Window winder RL	•		
	Window winder RR	•		
	Rear view mirrors	•		
	Radio (basic test only)	/		
	CD (basic test only)			
	Number of keys	2	1	
Kms	Central locking	/		
	Remote locking	•		
	Sat. nav. (basic test only)			_
	Reversing camera			

Make:	Honda	Model:	Civic				
Body Style: Sedan Rego No.: MJN24 WoF Expiry: 18 Nov 2026		Year:	2006				
		Rego Expiry:	11 Oct 2026 200,406 Kms				
		Odometer:					
Good No.: 27823263		VIN:	7AT08G0WX13100020				
Next Service:	201353	Service History: No					
liagnostic testing un	only. Consideration is made	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.				
(ey	= Rust		l- W C::6:				
	= Rust $C = C$ Γ = Paint defect $P = Pi$		3				
S R SC	SRI	S D R W	SDRW				
	(E)						
	$(0)_{\mathbb{F}}$		SD SD				
SDW		——————————————————————————————————————					
M			All Market				
			S PT SC				
0 D DT 00	10 II						
S R PT SC							
			S				
S R SC		R SC S	S				
3 K 3C		K 3C 3					
lote: some defects	and blemishes may not be	displayed in the diagra	ım				
• •	on Comments						
Rust in Spare V		at Dont in right oill					
Rust on Front S	Structure Under Bonne	et. Dent in right siii					
Conditions Dur	ring Body Inspection		Dry				
	e and Under Bonnet	Inspection Comm	ents				
	on Joint Boots Split						
Jnderbody Surf	ace Kusi						
Interior Comm	nents						
Seats:	Average						
Carpets:	Average						
Panels:	Average						
Dashboard:	Average	-					
General Comr							
Engine Whine -							
-	Lid Latch Broken						
		Dny					
Road Condition	ac I lurina lact I lriva						
Road Condition Engine Timing	ns During Test Drive	Dry Timing Chain					

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 04 Dec 2025

Samuel Weir

James Scott

Yes

No