

Basic Condition Guida

•	Report ID:	27,823,510	Version:	3
	Created:	02 Jan 2026		

Make:	Toyota	Model:	Aqua	-		Requires	
Body Style:	Hatchback	Year:	2016	OK Att		Attention	N/A
Rego No.:	PHY445	Rego Expiry:	30 Sep 2025	Engine			1
WoF Expiry:		Odometer:	241,311 Kms	Oil level			-
Good No.:	27823510	VIN:	7AT0H65YX22519456	Smoke & fumes			-
Next Service:	249540 kms	Service History:		Engine performance	V		-
ote: This report i	is not a warranty	,		Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Coolant condition	V		-
				Cooling performance	V		-
Key				Radiator / Hoses (visual)	/		
S = Scratch $R = Rust$ $C = Crack$ $* = Decals$ $W = Significant scuffs$ $D = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$				Transmission			
				Operation			
s)[Noise	-	-	<u> </u>
		\top		Clutch			~
			S	CV joints	/		<u> </u>
SDC /				Wheel bearings 🗸			<u> </u>
F	118			Brakes		ı	
				Performance	/		
				Hand brake			
P(Tyres (lowest observed tread depth of tyres)			
D Note: some defects and blemishes may not be displayed in the diagram				Left front	6.0 m		
				Right front			6.0 m
				Left rear	4.0 r		4.0 m
				Right rear	4.0		4.0 m
				Spare	Yes		
Body Inspect	tion Comments		Suspension				
rear shock le	eaking, Left rear tyre	flat,		Suspension performance	V		
				Steering performance	V		
				Shock absorbers		/	
Conditions Du	uring Body Inspection	1	Dry	Air Conditioning / Heater			
Under Carria	ge and Under Bonn	et Inspection Com	ments	Operation	/		
Carpet torn.				Electrical / Accessories			
				Head lights	V		
				Tail lights	V		
Interior Comments			Indicators	/			
Seats:	Average			Dashboard warning lights	1		
Carpets:	Average	verage		Wipers (front & rear)	~		
Panels: Average			Window winder FL	~			
Dashboard: Good				Window winder FR	~		
General Comments Reverse camera not working,				Window winder RL	1		
				Window winder RR	1		
				Rear view mirrors	1		
				Radio (basic test only)	1		
Road Condition	ons During Test Drive	Dry		CD (basic test only)	1	<u> </u>	
Thoad Conditions During Test Drive Dry							

I have read and understood this condition guide:

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 04 Dec 2025

Marlon Espena

Henry Manders

NAME			

No

Timing Chain

Yes

SIGNATURE		

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

2

1

1