

Basic Condition Guide

•	Report ID: 27,823,758		Version:	1	
	Created:	03 Dec 2025			

Make:	Mitsubishi	Model:	Pajero		01/	Requires	NI/A
Body Style:	Wagon	Year:	2007	Engine	OK	Attention	N/A
Rego No.:	HPB689	Rego Expiry:	17 Jan 2026	Oil level	V		
WoF Expiry:	06 May 2026	Odometer:	283,982 Kms	Smoke & fumes	V		
Good No.:	27823758	VIN:	7AT0CJ08X14003783	Engine performance	1		-
Next Service:	272000	Service History:	No	Noise	1		
ote: This report is	not a warranty			Coolant condition	1		
agnostic testing un	idertaken. The vehicle has b	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling performance	1		-
II mechanical inspe	ection prior to purchase and	d this can be arranged f	or an additional charge.	Radiator / Hoses (visual)	1		-
Key				Transmission		<u> </u>	
S = Scratch $R = Rust$ $C = Crack$ $* = Decals$ $W = Significant scuffs$ $D = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$				Operation	V		
- Dent 11	T = Tailit delect T = T		Noise	1		-	
s)(s	sc sc	Clutch			/	
			CV joints	1			
	$\mathcal{O}_{\mathcal{C}}$		(O) S SC	Wheel bearings	1		
S SC				Brakes			<u> </u>
M				Performance	V		
				Hand brake	1		
sc	10			Tyres (lowest observed tread depth of tyres)			
				Left front	3.8 mm		
S SC S S Note: some defects and blemishes may not be displayed in the diagram				Right front	5.0 mr		
				Left rear	7.8 mr		
				Right rear	8.1 mn		
				Spare	Yes		
Body Inspection		displayed in the diagre		Suspension			
	os on windscreen			Suspension performance	V	1	
				Steering performance	1		
				Shock absorbers	1		
Conditions Dur	ring Body Inspection		Dry	Air Conditioning / Heater		_	
	e and Under Bonnet	Inspection Comm		Operation		/	
our wheel drive				Electrical / Accessories			
Oil leak/ it's als Fransmission le	o leaking onto the exh	naust		Head lights	V		
ransmission le	ак			Tail lights	V		
Interior Comm	nents			Indicators	1		
Seats:	Good			Dashboard warning lights	1		
Carpets:	Good			Wipers (front & rear)	1		
Panels: Good			Window winder FL	V			
Dashboard: Good			Window winder FR	1			
General Comments				Window winder RL	1		
Due for service			Window winder RR	1			
VC not cold			Rear view mirrors	1			
				Radio (basic test only)	1		
Road Conditions During Test Drive Dry				CD (basic test only)			1
Engine Timing Mechanism					_		

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 02 Dec 2025

Janine Bell

Cameron Senior-Arnold

NAME			

No

✓ Yes

SIGNATURE

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

216,000 Kms