

Basic Condition Guide


•	Report ID:	27,823,770	Version:	1
	Created:	02 Dec 2025		

	ОК	Requires Attention	N/A
Engine	JI.	Accidon	14/71
Oil level	V		
Smoke & fumes	/		
Engine performance	V		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		6	3.0 mm
Right front		6	3.0 mm
Left rear		6	3.0 mm
Right rear		6	6.0 mm
Spare	Yes		
Suspension			
Suspension performance	>		
Steering performance	>		
Shock absorbers	>		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	/		
Wipers (front & rear)		'	
Window winder FL	/		
Window winder FR	/		
Window winder RL	V		
Window winder RR			
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking			'
Sat. nav. (basic test only)	/		
Reversing camera	/		

	JIIIEI	<u> </u>					
Make:	Toyota	Model:	Vitz				
Body Style:	Hatchback	Year:	2004				
Rego No.:	HCY599	Rego Expiry:	30 Oct 2025				
WoF Expiry:	10 Jun 2026	Odometer:	202,862 Kms				
Good No.:	27823770	VIN:	7AT0H63EX13040759				
Next Service:	due	Service History:	No				
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							
Key		·					

K	Έν
- 13	-Cy

S = Scratch* = DecalsW = Significant scuffs R = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Headlights dull/no tools/rust in spare wheel well/front bumper and bonnet misaligned/wiper in poor condition

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments

2wd/

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Road Condition	s During Test Drive	Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by: Uriah Pepene		
Published by:	Ricky (Ho-Kei) Wo	/ong
Inspection Date:	02 Dec 2025	

I have	read	and	understo	ood
this co	nditi	on a	uide	

NAME			

S	IG	N	Δ	TΙ	П	R	F	