

•	Report ID:	27,823,903	Version:	2	
	Created:	04 Dec 2025			

T	urne	S Bas	ic Condition Guide	Created: 04 Dec 2025		rsion: 2		
Make:	Mitsubishi	Model:	Galant			Requires		
Body Style:	Sedan	Year:	2008	OK Attent			N/A	
Rego No.:	HLS828	Rego Expiry:	31 Dec 2025	Engine				
WoF Expiry:	27 May 2026	Odometer:	191,055 Kms	Oil level				
Good No.:	27823903	VIN:	7AT0CJ0JX13109404	Smoke & fumes	/			
Next Service:		Service History:	No	Engine performance	<b>'</b>			
	is not a warranty	Service History.	110	Noise	V			
is report is a guid	de only. Consideration is ma		arts have not been dismantled or	Coolant condition				
agnostic testing I mechanical ins	undertaken. The vehicle has spection prior to purchase a	been driven up to 50km/ nd this can be arranged	Cooling performance	V				
ey				Radiator / Hoses (visual)				
-	R = Rust C =	Crack *= Deca	N = Significant scuffs	Transmission				
= Dent	PT = Paint defect P = Paint defect	Pin dent SC = Sto	ne Chips	Operation	<b>/</b>			
S PT SC	S SI	PT SC PT P SC	S DSC	Noise	<b>/</b>			
31100	0	77700 (77700		Clutch			/	
			S D PT SC	CV joints	<b>/</b>			
D. DT. OO	NA UN			Wheel bearings	V			
D PT SC				Brakes				
				Performance	V			
			S SC	Hand brake	V			
PT SC	18			Tyres (lowest observed tread depth of tyres)				
				Left front		•	1.5 mr	
SD				Right front	2.0 m		2.0 mr	
				Left rear	2.5 r		2.5 mr	
P SC	S	D SC S D SC	S S P SC	Right rear	3.0 n			
ote: some defect	ts and blemishes may not b	e displayed in the diagr	am	Spare	Yes			
	tion Comments	ie alspiayea in the alage		Suspension				
, ,	cover missing.			Suspension performance	V			
RF guard star	ting to rust.			Steering performance	1			
				Shock absorbers	1			
Conditions D	uring Body Inspection		Dry	Air Conditioning / Heater				
	ige and Under Bonne	et Inspection Comp		Operation	V			
	. <b></b>			Electrical / Accessories				
				Head lights	V			
				Tail lights	1			
Interior Comments				Indicators	1			
Seats: Good				Dashboard warning lights	1	-		
Carpets:	Good	<u> </u>		Wipers (front & rear)	1	-	$\vdash$	
Panels:	Good			Window winder FL	V		$\vdash$	
Dashboard: Good			Window winder FR	1	-			
General Comments				Window winder RL	1			
ulley area no			Window winder RR Window winder RR	1	-	$\vdash$		
lo retraction i					-	<i>\</i>		
				Rear view mirrors			<del> </del>	
				Radio (basic test only)	/		<u> </u>	

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Timing Chai	in	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Caleb Spicer Lee			
Published by:	Shanna Bullion			
Inspection Date:	01 Dec 2025			

I have read and understood this condition guide:

NAME			

SIGNATURE

Sat. nav. (basic test only) Reversing camera

CD (basic test only)

Number of keys

Central locking

Remote locking

2

1

•