

•	Report ID:	27,824,055	Version:	1
	Created:	08 Dec 2025		

4	uner	S Basi	c Condition Guide	Created: 08 Dec 2025	Ve	rsion: I	
				cicated. 00 DGC 2020			
Make:	Mazda	Model:	Axela		ОК	Requires Attention	N/A
Body Style:	Hatchback	Year:	2004	Engine	OK	Attention	13/73
Rego No.:	EYG353	Rego Expiry:	05 Nov 2026	Oil level	V		
WoF Expiry:	22 Dec 2026	Odometer:	177,143 Kms	Smoke & fumes	1		
Good No.:	27824055	VIN:	7A8C13J0709105741	Engine performance	-	 	
Next Service:	187,000 Kms	Service History:	No	Noise	1		
lote: This report i	•		Coolant condition	1			
iagnostic testing u	e only. Consideration is mad indertaken. The vehicle has b	een driven up to 50km/	Cooling performance	1			
	pection prior to purchase an	d this can be arranged f	Radiator / Hoses (visual)	1			
ey) D		l- W C::	Transmission			
	R = Rust C = C PT = Paint defect P = P		ls W = Significant scuffs ne Chips	Operation	· ·	<u> </u>	
				Noise	1		
s sc	S	DP* SP*	SD	Clutch			1
				CV joints			
	(0)		S	Wheel bearings	1		
S SC				Brakes		<u> </u>	
	119/11			Performance	· ·		
			sc	Hand brake			
s sc	HO			Tyres (lowest observed tread depth of tyres)			
	THE OF			Left front	5.7 mm		
			(Q)	Right front			6.4 mr
				Left rear		7	7.0 mr
S	W	DP SDP*	Right rear		6.9 mr		
Note: some defects and blemishes may not be displayed in the diagram				Spare	Yes		
	ion Comments	displayed in the diagra	4111	Suspension			
, ,				Suspension performance			
				Steering performance	1		
				Shock absorbers	1		
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater		<u>. </u>	
	ge and Under Bonnet	Inspection Comm	•	Operation	·		
2WD	-	· ·		Electrical / Accessories			
				Head lights	V		
				Tail lights	1	1	
Interior Com	ments			Indicators	1		
Seats:	Wear on front seats			Dashboard warning lights	1		
Carpets:	Large rip on drive	e rip on drivers side		Wipers (front & rear)	1		
Panels:	Right side door cards material pulling away			Window winder FL	1		
Dashboard:	Glue residue on centre of dashboard			Window winder FR	1		
General Comments				Window winder RL	1		
				Window winder RR	1		
				Rear view mirrors	1		
						+	

Road Condition	s During Test Drive	Dry		
Engine Timing N	Mechanism	Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Hoani Saunders			
Published by:	Miroslav Granich			
Inspection Date:	08 Dec 2025			

I have read and understood this condition guide:

NAME

SIGNATURE

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1

1 1

1

1