

•	Report ID:	27,824,249	Version:	3	
	Created:	18 Dec 2025			

Basic Condition Guide			Report ID: 27,824,249 Version: 3					
	UIIIEI			Created:	18 Dec 2025			
Make:	Honda	Model:	Accord			01/	Requires	N1/A
Body Style:	Sedan	Year:	2013			OK	Attention	N/A
Rego No.:	GZR144	Rego Expiry:	15 Nov 2026	Engine		V		
WoF Expiry:	01 Jan 2027	Odometer:	183,042 Kms	Oil level	ımor	1		
Good No.:	27824249	VIN:	JHMCU2680DC200250	Smoke a fames			-	
Next Service:	193,000 Kms	Service History:	No			1		-
Note: This report is not a warranty				Noise Coolant co	ndition	1		-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a						1		-
	pection prior to purchase an			Cooling pe		-		
Key					Hoses (visual)	/		
		Crack * = Deca	3	Transmiss	ion		I	1
D = Dent P	T = Paint defect P = P	Pin dent SC = Sto	ne Chips	Operation		/		ļ
S P SC		S	W	Noise		/		
				Clutch				
				CV joints		/		<u> </u>
S P SC W				Wheel bea	rings	/		
				Brakes				
				Performan	ce	/		<u> </u>
PT SC				Hand brake	2	/		
				Tyres (lowest observed tread depth of tyres)				
				Left front				5.9 mn
			S	Right front			(6.1 mn
	\angle			Left rear			(6.0 mn
D W S W SP				Right rear			(6.2 mn
Note: some defects	and blemishes may not be	e displayed in the diagra	am	Spare		Yes		
Body Inspect	ion Comments			Suspensio	n			
Front left wing	mirror housing cracke	ed		Suspension	n performance	/		
				Steering pe	erformance	/		
				Shock abso	orbers	1		
Conditions During Body Inspection Dry			Air Conditioning / Heater					
Under Carriage and Under Bonnet Inspection Comments				Operation		V		
2WD	-			Electrical /	'Accessories			
				Head lights		V		
				Tail lights		1		
Interior Comr	ments			Indicators		1		
Seats: Average			Dashboard warning lights					
Carpets: Wear on drivers side			Wipers (fro		1			
Panels: Interior door handles average		Window winder FL						
interior door nativies average		VVIII IGOVV VV	acııL		1	1		

Window winder FR Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking 1

Ī

1

1 2

1

1

In	Interior Comments		
Se	eats:	Average	
Ca	arpets:	Wear on drivers side	
Pa	nels:	Interior door handles average	
Da	ashboard:	Good	
General Comments			

Navigation has Australia maps only

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Jayson Rodriguez	<u>z</u>
Inspection Date:	18 Dec 2025	

have read and understood			
nis condition quide:	NAME	CICMATURE	