

•	Report ID:	27,824,310	Version:	3
	Created:	11 Dec 2025		

	Turners Basic Condition Guide			Report ID: 27,824,310 Version: 3			
	urner	S Basi	C Condition Guide	Created: 11 Dec 2025			
Make:	1	Model:	Impreze			Requires	
	Subaru		Impreza 2007		OK	Attention	N/A
Body Style:	Hatchback	Year:		Engine			
Rego No.:	JTT82	Rego Expiry:	27 Dec 2025	Oil level	/		
WoF Expiry:	08 Apr 2026	Odometer:	181,999 Kms	Smoke & fumes	/		
Good No.:	27824310	VIN:	JF1GH7KS58G002495	Engine performance	/		
Next Service: 192025 Service History: No			Noise	· ·			
Note: This report is	•	Coolant condition	· ·				
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling performance	1		
				Radiator / Hoses (visual)	1		
Key S = Scratch R	= Rust C = 0	Crack * = Deca	ls W = Significant scuffs	Transmission			
	T = Paint defect P = F		•	Operation			
	· · · · · · · · · · · · · · · · · · ·	DT D		Noise	-		
DC	W	PT P PT	WS	Clutch			1
			(CDT CW)	CV joints	1		
			SPTCW	Wheel bearings	1		
SDPTCW				Brakes			
	19/ 11	Performance					
			SDPT	Hand brake			
D SC R PT W S D D W				Tyres (lowest observed tread depth of tyres)			
				Left front	6.0 mr		
				Right front	6.0 mi		
				Left rear	5.0 mi		
				Right rear	6.0 mi		
Note: some defects and blemishes may not be displayed in the diagram				Spare	Yes		
	ion Comments	e dispiayed in the diagra		Suspension			
Right side mirr				Suspension performance	· ·		
Tright one film of damaged.				Steering performance	1		
				Shock absorbers	V		
Conditions Du	ring Rody Inspection		Wet	Air Conditioning / Heater			
Conditions During Body Inspection Wet Under Carriage and Under Bonnet Inspection Comments			Operation		· ·		
Engine oil leaks. Exhaust has been modified.				Electrical / Accessories			
•				Head lights	· ·		
				Tail lights	1		
Interior Comments				Indicators	1		
Seats: Average			Dashboard warning lights	1			
Carpets:	driver floor torn.			Wipers (front & rear)	1		
Panels:			Window winder FL	· ·			
	cis. Avelage			WINDOW WINDER TE			

	Seats:	Average				
	Carpets:	driver floor torn.				
	Panels:	Average				
	Dashboard:	Average				
	General Comm	ients				
	W/S stone chip out of CVA. Squealing noise when A/C on. Rear wiper washer not working.					
	Road Conditions During Test Drive		Wet			
	Engine Timing Mechanism Evidence of Cam Belt Replacement		Cambelt			
			✓ Yes	No	100,690	Kms
	Inspected by:	Eleoit Kumar				

SIGNATURE		

1

1 2

1

1

Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

I have read	and	unc	lerstood
this condit	ion g	guide	2:

Inspection Date: 03 Dec 2025

Published by:

Sam Huang