


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2015
Rego No.:	RMF378	Rego Expiry:	21 Sep 2026
WoF Expiry:	02 Jan 2027	Odometer:	179,404 Kms
Good No.:	27824375	VIN:	MMAWJKL10GH008606
Next Service:	189370	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

4x4

Interior Comments

Seats:	driver bottom pad ripped
--------	--------------------------

Carpets:	Average
----------	---------

Panels:	Average
---------	---------

Dashboard:	Average
------------	---------

General Comments

Road Conditions During Test Drive	Dry
-----------------------------------	-----

Engine Timing Mechanism	Timing Chain
-------------------------	--------------

Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
----------------------------------	------------------------------	-----------------------------	-----

Inspected by:	Uriah Pepene
---------------	--------------

Published by:	Bobby Zhong
---------------	-------------

Inspection Date:	08 Jan 2026
------------------	-------------

I have read and understood
this condition guide:

NAME _____

Report ID:	27,824,375	Version:	1
Created:	18 Jan 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	7.5 mm		
Right front	7.5 mm		
Left rear	5.0 mm		
Right rear	5.0 mm		
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE _____