

•	Report ID:	27,824,560	Version:	1
	Created:	02 Dec 2025		

GA TI	ntuet	S Basi	ic Condition Guide	Created:	02 Dec 2025	VC	131011.		
					1				
Make:	Honda	Model:	FIT			ОК	Requires Attention	N/A	
Body Style:	Hatchback	Year:	2007	Engine		<u> </u>	7	,, .	
Rego No.:	HHT436	Rego Expiry:	12 Sep 2026	Oil level		V			
WoF Expiry:	03 Apr 2026	Odometer:	161,950 Kms	Smoke & fr	umes				
Good No.:	27824560	VIN:	7AT08G2YX14002668	Engine per		1			
Next Service:	170,700Kms	Service History:	No	Noise		1			
Note: This report is				Coolant co	endition	1			
This report is a guide diagnostic testing u	e only. Consideration is mad ndertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a		erformance	1			
ull mechanical insp	ection prior to purchase an	d this can be arranged f 	for an additional charge.		Hoses (visual)	1			
Key			la W. Chaifeanta ff	Transmiss					
	C = Rust $C = CC = Rust$ $C = Rust$			Operation		V			
	T diffe defect 1 1	mrdent se sto	The emps	Noise		1			
sc	s	R SC S SC	SC	Clutch				1	
				CV joints		1			
	$(0)_{\mathbb{F}}$		S SC W	Wheel bea	rinas	1			
S SC W					Brakes				
M				Performan	ce	V			
						1			
s sc	10			Hand brake  Tyres (lowest observed tread depth of tyres)					
				Left front	est observed tread			4 mm	
S D SC S SC S SC				Right front	-			4 mm	
				Left rear				4 mm	
				Right rear				4 mm	
Note: some defects	and blemishes may not be	displayed in the diagra	am .	Spare		N/A			
Note: some defects and blemishes may not be displayed in the diagram  Body Inspection Comments					on				
LF, LR, RF door corrosion.					n performance	V			
				•	erformance	1			
				Shock abso		1			
Conditions Du	ring Body Inspection		Wet		tioning / Heater				
	ge and Under Bonnet	Inspection Comm		Operation	<u> </u>	V			
Underbody surface rust.					Electrical / Accessories				
•				Head light		V			
				Tail lights		1			
Interior Comr	ments			Indicators		1			
interior Comments				marcutors				<u> </u>	

Interior Comm	ents		

## Seats: Average Carpets: Average Panels: Average Dashboard: Average **General Comments**

## Rear window washer not working.

Both side wing mirror cannot fold.

Road Condition	s During Test Drive	Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Bobby Zhong	
Published by:	Bobby Zhong	
Inspection Date:	02 Dec 2025	

SIGNATURE			

1

1

V

1 1

2

1 1

Dashboard warning lights Wipers (front & rear)

Window winder FL

Window winder FR

Window winder RL

Window winder RR

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

Rear view mirrors Radio (basic test only)

·
I have read and understood
this condition guide:

NAME	