

•	Report ID:	27,824,685	Version:	1	
	Created:	01 Dec 2025			

		Daa:		, = . , = =				
	nuer	S Basi	c Condition Guide	Created:	01 Dec 2025			
Make:	Mazda	Model:	Bongo				Requires	
Body Style:	Van	Year:	2015			OK	Attention	N/A
Rego No.:	MFJ538	Rego Expiry:	24 Feb 2026	Engine				
WoF Expiry:	29 Nov 2026	Odometer:	175,848 Kms	Oil level				
Good No.:	27824685	VIN:	7AT0C10WX19211966	Smoke & fu		<i>\</i>		
Next Service:	179,000 Kms	Service History:	No	Engine per	formance	/		
		Service History.		Noise				
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or				Coolant co		✓		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.			Cooling pe	rformance	/			
Key				Radiator / I	Hoses (visual)			İ
•	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmiss	ion			
D = Dent PT	= Paint defect $P = P$	in dent SC = Stor	ne Chips	Operation		/		
SC SC DSC			D.SC.	Noise		/		
				Clutch		/		
			PT	CV joints		✓		
	TO COL			Wheel bea	rings	/		
s d				Brakes				
S SC				Performan	ce	~		
			SSC	Hand brak	e	/		
D SC				Tyres (lowest observed tread depth of tyres)				
S D SC			Left front				5 mm	
			Right front		5 mm			
				Left rear			3	3.5 mm
SC D SC S D SC P SC				Right rear		4.5 mm		
Note: some defects a	nd blemishes may not be	displayed in the diagra	ım	Spare		Yes		
Body Inspection				Suspensio	n			
Stonechips in wi	ndscreen.			Suspension	n performance	/		
FR wheel arch worn.				Steering p	erformance	/		
Window tints in p	boor condition .			Shock abso	orbers	/		
Conditions Duri	ng Body Inspection		Dry	Air Condit	ioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
					'Accessories			
				Head light	1			
				Tail lights		· /		
Interior Comm	ents			Indicators		· /		
Seats: Poor, drivers seat base torn.				l warning lights	· ·			
Carpets: Average			Wipers (fro		-			
					,			

	Interior Comments		
	Seats: Poor, drivers seat base torn.		
Carpets:		Average	
	Panels:	ls: Average	
	Dashboard:	Average, steering wheel worn.	
General Comments			

Rear window washer not working.

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by: Troy Smith		
Published by: Troy Smith		
Inspection Date:	01 Dec 2025	

NAME	SIGNATURE

Window winder FL Window winder FR Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking 1

1

1

I have read and understood this condition guide: