

Basic Condition Guide


•	Report ID:	27,824,882	Version:	1
	Created:	16 Dec 2025		

		ОК	Requires Attention	N/A
	Engine			
	Oil level	V		
	Smoke & fumes	1		
99	Engine performance	1		
	Noise	1		
	Coolant condition	V		
ends a	Cooling performance	1		
	Radiator / Hoses (visual)	1		
scuffs	Transmission			
. scans	Operation	V		
	Noise	1		
S	Clutch			1
22	CV joints	V		
sc	Wheel bearings	1		
	Brakes		<u> </u>	
	Performance	V		
SC	Hand brake	1		
	Tyres (lowest observed tread	depth of	tvres)	
	Left front			1.2 mr
s	Right front			5.0 mr
	Left rear			3.9 mr
D	Right rear			1.5 mr
	Spare	No		
	Suspension			
	Suspension performance	V		
	Steering performance	1		
	Shock absorbers	1		
	Air Conditioning / Heater			
	Operation Operation	V		
	Electrical / Accessories			
	Head lights		<u> </u>	1
	Tail lights	-		
	Indicators			
		V		
	Dashboard warning lights	1		
	Wipers (front & rear) Window winder FL	V		
	Window winder FR	<i>V</i>		
	Window winder RL	V		
	Window winder RR	/		
	Rear view mirrors	/		
	Radio (basic test only)	/	-	
	CD (basic test only)			
	Number of keys	1	1	1
Kms	Central locking	/		
	Dana aka la akka a	/		
	Remote locking			
	Sat. nav. (basic test only) Reversing camera			

Make:	BMW	Model:	3201			
Body Style:	Sedan	Year:	2011			
Rego No.:	JZM885	Rego Expiry:	25 Feb 2026			
WoF Expiry:	09 Dec 2025	Odometer:	108,319 Kms			
Good No.:	27824882	VIN:	WBAPG36090NM94099			
Next Service:	09/06/25	Service History:	No			
Note: This report is r	not a warranty					
diagnostic testing und		een driven up to 50km/h	orts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.			

Key

S = Scratch C = Crack* = DecalsW = Signific R = RustD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Minor stonechips on windscreen

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Rear wheel drive Oil leak

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Due for service since 09/06/25

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Cameron Senior-	Arnold
Published by:	Janine Bell	
Inspection Date:	03 Dec 2025	

l have	read	and	unde	rstood
this co	nditi	on a	uide	

NAME			