

Report ID:	27,824,946	Version:	2
Created:	09 Dec 2025		

OK

Requires Attention

N/A

Mako	Mozdo	Model:	Axela
Make:	Mazda		
Body Style:	Hatchback	Year:	2004
Rego No.:	EHE813	Rego Expiry:	11 Jan 2026
WoF Expiry:	25 Sep 2026	Odometer:	282,973 Kms
Good No.:	27824946	VIN:	7A8C13J0707107988
Next Service:	293, 005 Kms	Service History:	No
liagnostic testing ur	only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.
Кеу			
S = Scratch R	= Rust $C = C$	rack *= Deca	ls W = Significant scuff
D = Dent P	$\Gamma = Paint defect  P = Pi$	in dent SC = Sto	ne Chips
SC	S	sc sc	S SC
	$\sim$		PT SC
S PT SC			
$\neg \neg \rho$	18		
1			PT SC
sc			
			S SC
P SC	S	SC P SC	S SC
		1 00	
	and blemishes may not be	displayed in the diagra	am 
	on Comments		a whall wall
RF fog light len LH mirror cover		ust starting in spar	e wneel well.
			T_
	ring Body Inspection		Dry
	e and Under Bonnet	Inspection Comm	nents
Minor oil leak.			
Interior Comn	nents		
Seats:	Good		
Carpets:	Good		

Engine			
Oil level	<b>'</b>		
Smoke & fumes	<b>/</b>		
Engine performance	1		
Noise	<b>/</b>		
Coolant condition	/		
Cooling performance	~		
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	~		
Noise	~		
Clutch			<b>V</b>
CV joints	~		
Wheel bearings	<b>'</b>		
Brakes			
Performance	~		
Hand brake	<b>'</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		(	6.5 mm
Right front			7.0 mm
Left rear			3.5 mm
Right rear		4	4.0 mm
Spare	Yes		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	~		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>'</b>		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	1		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	•		
Window winder RL	1		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	/		
CD (basic test only)	•		<u> </u>
Number of keys	2	·	
Central locking	•		
Remote locking	1		
Sat. nav. (basic test only)			<b>/</b>
Reversing camera			

Road Conditions During Test Drive		Dry		
Engine Timing I	Mechanism	Timing Chair	n	
Evidence of Car	n Belt Replacement	Yes	No	Kms
Inspected by:	Caleb Spicer Lee			
Published by:	Shanna Bullion			
Inspection Date:	02 Dec 2025			

I have read and understood this condition guide:

Panels:

Dashboard:

**General Comments** One key fob not working.

Good

Good

NAME

SIGNATURE