

| Report ID: | | 27,824,967 | Version: | 1 | |
|------------|----------|-------------|----------|---|--|
| | Created: | 02 Dec 2025 | | | |

| Basic Condition Guide | | | | | 27,824,967 | Ve | rsion: 1 | |
|--|--|---------------------------|-------------------|--|--------------------------|----------|-----------|---------------------------------------|
| | Ulliel | | | Created: | 02 Dec 2025 | | | |
| Make: | Nissan | Model: | Navara | | | | Requires | |
| Body Style: | Utility | Year: | 2016 | Fu aring | | OK | Attention | N/A |
| Rego No.: | KBC818 | Rego Expiry: | 28 Feb 2026 | Engine | | · | | 1 |
| WoF Expiry: | 14 Aug 2026 | Odometer: | 80,430 Kms | Oil level | | - | | - |
| Good No.: | 27824967 | VIN: | MNTCA2D23A0000560 | Smoke & fu | | / | <u> </u> | _ |
| Next Service: | 90,000 Kms | Service History: | No | Engine per | formance | / | | - |
| Note: This report is not a warranty | | | Noise | 11.1 | <i>'</i> | | - | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | Coolant co | | / | | - |
| | | | | Cooling pe | | / | | - |
| еу | | | | | Hoses (visual) | / | | |
| | | Crack *= Deca | | Transmiss | ion | | ı | |
| = Dent F | PT = Paint defect P = P | Pin dent SC = Sto | ne Chips | Operation | | / | | |
| | W | S | S | Noise | | / | | <u> </u> |
| | | | | Clutch | | / | | _ |
| | \ _\(\int \) (\(\int \) (\(\int \) (\(\int \) (\(\int \) \) | | M_{-} | CV joints | | | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| | | | | Wheel bea | rings | / | | |
| $-\!$ | | | | Brakes | | | | |
| | | \mathbb{N} | | Performan | ce | / | | |
| | | | | Hand brake | e | / | | |
| | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | Left front | | 7.6 m | | | |
| P W SPT | | | | Right front | | 6.9 r | | |
| | | | | Left rear | | 3.0 | | 3.0 r |
| | | | | Right rear | | 2.5 r | | 2.5 r |
| ote: some defect: | s and blemishes may not be | e displayed in the diagra | am | Spare | Spare Yes | | | |
| Body Inspect | tion Comments | | | Suspensio | n | | | |
| | ight isn't working | | | Suspension | n performance | / | | |
| Tiny stone chip in front windscreen | | | | Steering pe | erformance | / | | |
| | | | | Shock abso | orbers | ' | | |
| Conditions During Body Inspection Dry | | | Air Condit | ioning / Heater | | | | |
| Under Carriage and Under Bonnet Inspection Comments | | | | Operation | | ' | | |
| 2WD | | | | Electrical / | Electrical / Accessories | | | |
| | | | | Head lights | 5 | ' | | |
| | | | | Tail lights | | 1 | | |
| Interior Comments | | | | Indicators | | 1 | | |
| Seats: Stains on front seats. Rip on drivers seat | | | Dashboard | l warning lights | 1 | | | |
| Seats: | Otalis on hone se | Good | | | | | t | - |
| Carpets: | | | | Wipers (fro | nt & rear) | / | | |
| | | | | Wipers (fro | | V | | |
| Carpets: | Good | | | | inder FL | _ | | |

| | Seats: | Stains on front seats. Rip on drivers seat |
|------------------|------------|--|
| | Carpets: | Good |
| | Panels: | Good |
| | Dashboard: | Good |
| General Comments | | |
| | | |
| | | |

| Road Conditions During Test Drive | | Dry | | |
|-----------------------------------|----------------------------------|--------------|----|-----|
| Engine Timing Mechanism | | Timing Chain | | |
| Evidence of Can | Evidence of Cam Belt Replacement | | No | Kms |
| Inspected by: | Hoani Saunders | | | |
| Published by: | Miroslav Granich | | | |
| Inspection Date: | 01 Dec 2025 | | | |

| have read and understood |
|--------------------------|
| this condition quide |

| NAME | | | |
|------|--|--|--|

•

1 1

1

Window winder RR Rear view mirrors

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking