


Make:	Mazda	Model:	Mazda6
Body Style:	Hatchback	Year:	2004
Rego No.:	CHA422	Rego Expiry:	10 Apr 2026
WoF Expiry:	26 Nov 2026	Odometer:	215,632 Kms
Good No.:	27824980	VIN:	JM0GG103100156620
Next Service:	No record	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left side of front bumper is not fitted correctly.
Minor spider rusts and dents on roof. Right door mirror cover is cracked.
Spare tyre is punctured.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Minor surface rust is developing under body.

Interior Comments

Seats: Right front is torn.
Carpets: Good
Panels: Good
Dashboard: Good

General Comments

AC is not cold. Left rear window is not operating. Roof racks in boot.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Yuki Itohara
Published by:	Glen Charlton
Inspection Date:	10 Dec 2025

I have read and understood
this condition guide:

NAME _____

Report ID:	27,824,980	Version:	1
Created:	11 Dec 2025		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			6.0 mm
Right front			6.0 mm
Left rear			6.0 mm
Right rear			6.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL		✓	
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE _____