

Basic Condition Guide

•	Report ID:	27,825,016	Version:	1
	Created:	11 Dec 2025		

	OK	Requires Attention	
Engine		Attention	14/74
Oil level	/		
Smoke & fumes	1		
Engine performance	/		
Noise	V V		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	_		
Transmission			
Operation	/		
Noise	/		
Clutch	_		
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	/		
Hand brake	1		
Tyres (lowest observed tread d	enth of	tvres)	
Left front	Cpuroi		5 mm
Right front			5 mm
Left rear			5 mm
Right rear			5 mm
Spare			
Suspension			
Suspension performance	/		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/	1	
Tail lights	/		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	·		
Window winder FL			
Window winder FR	V		
Window winder RL	<i>'</i>		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			
Number of keys	1	<u> </u>	
Central locking	· /	1	
Remote locking	·		
Sat. nav. (basic test only)			
Reversing camera	1		<u> </u>
neversing carriera	_		


Make:	Subaru	Model:	Outback
Body Style:	Wagon	Year:	2007
Rego No.:	GPP587	Rego Expiry:	05 May 2026
WoF Expiry:	07 Feb 2026	Odometer:	189,786 Kms
Good No.:	27825016	VIN:	7AT0GF16X12046918
Next Service:	194,000 kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

Rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Headlights faded

Rear spoiler paint defect

FR door interior seal torn

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

4wd

Engine oil leak

Transmission oil leak

Underbody surface rust

Interior Comments		
Seats: FR seat back trim torn		
Carpets: Good		
Panels:	FR and FL door trims scuffed	
Dashboard:	torn	
General Comments		

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt	,	
Evidence of Cam Belt Replacement		✓ Yes	No	163,512 Kms
Inspected by:	Vasanthakumar M	/layilswamy		
Published by:	Vasanthakumar M	layilswamy		
Inspection Date:	11 Dec 2025			

I hav	ve read	and	understood
thic	conditi	on a	uide.

NAME			

SI	GN	AT	URF	