


Make:	Daihatsu	Model:	Boon
Body Style:	Hatchback	Year:	2006
Rego No.:	KWZ826	Rego Expiry:	14 Jan 2026
WoF Expiry:	15 Jan 2026	Odometer:	181,830 Kms
Good No.:	27825063	VIN:	7AT04727X17010533
Next Service:	0km	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Front bumper refit,R/R quarter impact damaged,Rear bumper damaged,Water&rust in spare tyre area,L/F wing mirror glass missing/damaged,Windscreen crack in&out cva,

Conditions During Body Inspection

Dry

## Under Carriage and Under Bonnet Inspection Comments

FWD,Excessive oil leaks underside underside,Surface rust underside,Front rotors worn,

## Interior Comments

Seats:	Poor
Carpets:	Poor
Panels:	Poor
Dashboard:	Average

## General Comments

Radiator reservoir coolant not clean,Front guards rusty,hi stop&L/R brake light not working,

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Imraan Bryant
Published by:	Imraan Bryant
Inspection Date:	01 Dec 2025

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Report ID:	27,825,063	Version:	1
Created:	01 Dec 2025		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance		✓	
Noise	✓		
Coolant condition		✓	
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			3 mm
Right front			3 mm
Left rear			6 mm
Right rear			6 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		