

Basic Condition Guida

•	Report ID:	27,825,207	Version:	1
	Created:	05 Dec 2025		

	ntuet	S Bas	ic Condition Guide	Created: 05 Dec 2		131011.		
Make:	Toyota	Model:	Landcruiser Prado			Requires		
Body Style:	SUV	Year:	2007	Frains	OK	Attention	N/A	
Rego No.:	RKT717	Rego Expiry:	27 Feb 2026	Engine			1	
WoF Expiry:	17 Dec 2026	Odometer:	179,706 Kms	Oil level Smoke & fumes	<i>'</i>		-	
Good No.:	27825207	VIN:	JTEBZ25J700142126		V		-	
Next Service:	186,700 Kms	Service History:	Yes	Engine performance	<i>V</i>			
Note: This report i	s not a warranty			Noise Coolant condition	<i>V</i>		-	
This report is a guid diagnostic testing u	e only. Consideration is mad Indertaken. The vehicle has b	le for age and mileage. F peen driven up to 50km		-		-		
ull mechanical insp	oection prior to purchase ar	nd this can be arranged	Cooling performance			-		
Кеу				Radiator / Hoses (visu	al)			
		Crack *= Deca		Transmission		l	T	
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips				Operation	· ·		-	
SC W	F	S D PT S	C S D PT W	Noise			1	
				Clutch			"	
	(O)E		SPTW	CV joints	<i>V</i>			
S D SC W				Wheel bearings				
			HIV	Brakes		l		
			SC	Performance	<i>'</i>			
				Hand brake				
SC		\longrightarrow		Tyres (lowest observed tread depth of tyres)				
D SC W P SC S P SC				Left front		5.1 mm		
				Right front		5.8 mm		
				Left rear		2.9 mm		
				Right rear		3.4 mm		
	s and blemishes may not be	e displayed in the diagr	am	Spare	Yes			
, ,	ion Comments			Suspension		I		
Stone chip in f	ront windscreen			Suspension performa				
				Steering performance				
			T_	Shock absorbers	•			
	uring Body Inspection		Dry	Air Conditioning / Heater				
	ge and Under Bonne	t Inspection Comr	nents	Operation	•			
4WD				Electrical / Accessor	ies	<u> </u>		
				Head lights				
				Tail lights	<i>'</i>			
Interior Com				Indicators	V			
Seats:	Large rip on drive	ers seat		Dashboard warning li	ghts 🗸			
Carpets:	Drivers side avera	_ -		Wipers (front & rear)	· ·			
Panels:	Scuffs in boot are	ea		Window winder FL	· ·			
Dashboard:	Good			Window winder FR	•		<u> </u>	
General Comments				Window winder RL		'		
8 Seats	don't work off	ovvitob		Window winder RR		~		
rear windows	don't work off master :	SWITCH		Rear view mirrors	/			

I have read and understood
this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Hoani Saunders

Miroslav Granich

03 Dec 2025

Engine Timing Mechanism

Inspected by:

Published by:

Inspection Date:

Dry

Cambelt

✓ Yes

NAME		

No

3

1

1

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

150,125 Kms