

ide

Report ID:	27,825,224	Version:	1
Created:	03 Dec 2025		

ack		ОК	Requires Attention	N/A	
	Engine				
ıg 2026	Oil level	/			
801 Kms	Smoke & fumes	V			
PEKUA5G017862	Engine performance	/			
	Noise	/			
	Coolant condition	1			
not been dismantled or ld. The Vendor recommends a	Cooling performance	1			
litional charge.	Radiator / Hoses (visual)	1			
W = Significant scuffs	Transmission			<u> </u>	
s = Significant scuits	Operation	V			
	Noise	/			
S SC	Clutch			1	
	CV joints	/			
S SC	Wheel bearings	1			
	Brakes		<u> </u>		
791K	Performance	V			
sc	Hand brake	1			
	Tyres (lowest observed tread		tures)		
	Left front	Першо		2.0 mn	
PT SC	Right front			2.4 mm	
	Left rear			2.6 mm	
D SC	Right rear			2.4 mm	
		Yes		2.4 11111	
	Spare Yes Suspension				
	Suspension performance	V		l	
	Steering performance	1			
	Shock absorbers	1			
	Air Conditioning / Heater	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	l	I	
	Operation				
	Electrical / Accessories		Ī	ı	
	Head lights	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
	Tail lights	-			
	Indicators	/	-		
	Dashboard warning lights	/			
	Wipers (front & rear)	/	-		
	Window winder FL	/	-		
	Window winder FR	/			
	Window winder RL	/			
	Window winder RR	/	-		
	Rear view mirrors	/			
	Radio (basic test only)	/			
	CD (basic test only)			'	
	Number of keys	1			
Kms	Central locking		~		
	Remote locking		~		
	Sat. nav. (basic test only)			/	

O T	nuer	5
Make:	Subaru	Ν


Basic	Condition	Gui
Dasic	Condition	Oui

/lodel: Outba SUV 2004 Body Style: Year: **CJF868** 08 Au Rego No.: Rego Expiry: 267,3 WoF Expiry: 05 Mar 2026 Odometer: 27825224 VIN: JF2B Good No.: Next Service: 05/03/25 Service History: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have r diagnostic testing undertaken. The vehicle has been driven up to 50km/h from col full mechanical inspection prior to purchase and this can be arranged for an add

* = DecalsS = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Minor stonechips on windscreen

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

All wheel drive Oil leak

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Due for service since 05/03/25 Remote locking not working

Central locking not working for drivers door

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Cameron Senior-	-Arnold	
Published by:	Janine Bell		
Inspection Date:	03 Dec 2025		

I have read and understood
this condition guide:

NAME			