

-	Report ID:	27,825,538	Version:	1
	Created:	03 Dec 2025		

EA T	urner	Basi	c Condition Guide	Report ID:	27,825,538	Ve	rsion: 1	
	oniei			Created:	03 Dec 2025			
Make:	Nissan	Model:	Qashqai			ОК	Requires Attention	NI/A
Body Style:	SUV	Year:	2013	Engine		UK	Attention	N/A
Rego No.:	GZM815	Rego Expiry:	11 Nov 2026	Oil level		· /		1
WoF Expiry:	21 Nov 2026	Odometer:	122,688 Kms	Smoke & fu	ımes	1		+
Good No.:	27825538	VIN:	SJNFBAJ10A2773232	Engine per		· /	-	+-
Next Service:	116,000 Kms	Service History:	Yes	Noise	Torriditee	V		+-
lote: This report is	s not a warranty		1	Coolant co	andition	1		+
liagnostic testing u	ndertaken. The vehicle has b	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a		erformance	1		+
ıll mechanical insp	ection prior to purchase an	d this can be arranged f 	or an additional charge.		Hoses (visual)	1		+
Key				Transmiss				
	C = Rust $C = CC = Rust$ $C = C$			Operation	1011	· /		Т
				Noise		1		+
SDW	s	DPS		Clutch				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
				CV joints		1		+
	$(0)_{\mathbb{F}}$			Wheel bea	rinas	1		+
s sc				Brakes	95			
M				Performan	ce	V		T
				Hand brak		1		+
	10			Tyres (lowest observed tread depth of tyres)				
S				Left front		2.4 mm		
				Right front	 :	3.4 mn		
						4.0 m		
			S	Right rear				4.2 mm
Note: some defects and blemishes may not be displayed in the diagram				Spare		Yes		
	ion Comments	,		Suspension	on			
Stone chip in fr	ont windscreen			Suspensio	n performance	1		
	bumper trim missing	oft aids of front hum	onor	Steering p	erformance	1		
From len guard	flare detaching and le	en side of from buri	ipei	Shock abso	orbers	1		
Conditions During Body Inspection Wet				Air Condit	tioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation		1		Т
2WD				Electrical	/ Accessories			
				Head light	S	1		T
				Tail lights		1		
Interior Comments			Indicators		1			
Seats:	Average			Dashboard	d warning lights	1		
Carpets:	Average		 -	Wipers (fro	ont & rear)	1		1
Panels:	Average			Window w	inder FL	~		1
Dashboard: Good			Window w	inder FR	~			
General Com	ments			Window w	inder RL	1		1
Partial service I	artial service history				inder RR	1		
						1	 	+

Road Condition	s During Test Drive	Wet
Engine Timing I	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Mathew Green	
Inspection Date:	03 Dec 2025	

have read and understood
this condition quide

NAME			

S	IG	N	Δ.	TΙ	IR	F	

Rear view mirrors

Number of keys

Central locking Remote locking

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

•

1 2

•

•