

Report ID: 27,826,439		27,826,439	Version:	1
	Created:	29 Dec 2025		


	ОК	Requires Attention	N/A
Engine			_
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	V		
Brakes			
Performance	1		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7 mm
Right front			7 mm
Left rear		(6.0 mm
Right rear			5.0 mm
Spare	N/A		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL			/
Window winder RR			
Rear view mirrors	>		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera	1		

Make:	Honda	Model:	CR-Z
Body Style:	Hatchback	Year:	2010
Rego No.:	QCG521	Rego Expiry:	20 Jan 2026
WoF Expiry:	30 Dec 2026	Odometer:	122,888 Kms
Good No.:	27826439	VIN:	7AT08GCLX23001804
Next Service:	132,000km	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key * = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Front Wheel Drive

Interior Comments		
Seats:	Average	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Fresh Warrant of Fitness Fresh Service

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Imraan Bryant	
Published by:	Jesh Singh	
Inspection Date:	09 Dec 2025	

I have read and understood
this condition guide:

NAME			