

Report ID:	27,828,279	Version:	1
Created:	03 Dec 2025		


Make:	Toyota	Model:	Hiace
Body Style:	Van	Year:	2009
Rego No.:	KZM235	Rego Expiry:	26 Sep 2026
WoF Expiry:	03 Sep 2026	Odometer:	349,629 Kms
Good No.:	27828279	VIN:	7AT0H60FX17045832
Next Service:	355,471kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Water in right head light. Both head lights have minor cracks. Rear badge is missing. Rear mirror on tail gate is missing.

Conditions During Body Inspection	Dry
-----------------------------------	-----

## Under Carriage and Under Bonnet Inspection Comments

Both sill lips have dents . Leaking from around engine and transmission.

## Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

## General Comments

High mount stop light is not operating. Right air vent is broken. Right front seat base pad is torn and not fitted correctly. Rear seat belts had been removed( Parts in the vehicle( missing screw). Rear seat is not fitted properly. Clutch is worn.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No 288,096 Kms
Inspected by:	Yuki Itohara
Published by:	Shayla King
Inspection Date:	03 Dec 2025

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch		✓	
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			4.0 mm
Right front			4.5 mm
Left rear			2.5 mm
Right rear			4.5 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights		✓	
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_