

| Report ID: | 27,828,365 | Version: | 1 |
|------------|-------------|----------|---|
| Created: | 02 Dec 2025 | | |


| | ОК | Requires Attention | N/A |
|------------------------------|-------------------|--|----------|
| Engine | | | |
| Oil level | / | | |
| Smoke & fumes | \(\frac{1}{V} \) | | |
| Engine performance | / | | |
| Noise | / | | |
| Coolant condition | / | | |
| Cooling performance | ~ | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | / |
| CV joints | / | | |
| Wheel bearings | V | | |
| Brakes | | | |
| Performance | V | | |
| Hand brake | / | | |
| Tyres (lowest observed tread | depth of | tyres) | |
| Left front | | | 1.0 mm |
| Right front | | 3 | 3.6 mm |
| Left rear | | (| 6.6 mm |
| Right rear | | | 2.6 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | 1 | | |
| Shock absorbers | 1 | | |
| Air Conditioning / Heater | | | |
| Operation | | V | |
| Electrical / Accessories | | | |
| Head lights | V | | |
| Tail lights | V | | |
| Indicators | 1 | | |
| Dashboard warning lights | 1 | | |
| Wipers (front & rear) | 1 | | |
| Window winder FL | 1 | | |
| Window winder FR | 1 | | |
| Window winder RL | · | | |
| Window winder RR | 1 | | |
| Rear view mirrors | 1 | | |
| Radio (basic test only) | 1 | | |
| CD (basic test only) | | | 1 |
| Number of keys | 1 | <u> </u> | |
| Central locking | · / | 1 | |
| Remote locking | 1 | - | |
| Sat. nav. (basic test only) | + | | |
| | | - | 1 |
| Reversing camera | | | |

| Make: | Toyota | Model: | Corolla |
|---------------|-------------|------------------|-------------------|
| Body Style: | Wagon | Year: | 2006 |
| Rego No.: | JJR160 | Rego Expiry: | 15 Apr 2026 |
| WoF Expiry: | 25 Sep 2026 | Odometer: | 191,738 Kms |
| Good No.: | 27828365 | VIN: | 7AT0H607X15007682 |
| Next Service: | 187,000 Kms | Service History: | No |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Side skirts loose

| Conditions During Body Inspection | Dry |
|---|------|
| Under Carriage and Under Bonnet Inspection Comm | ents |
| 2WD | |
| Oil seen | |

Interior Comments Stains. Wear on front seats Seats: Good Carpets: Scuffs on boot lid panel Panels: Dashboard: Small blemish on plastic stereo surround trim

General Comments

AC- not cold

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|------------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Hoani Saunders | |
| Published by: | Miroslav Granich | |
| Inspection Date: | 02 Dec 2025 | |

| I have read and understood |
|----------------------------|
| this condition guide: |

| NAME | | | |
|------|--|--|--|