

## **Basic Condition Guide**

•	Report ID:	27,828,618	Version:	2	
	Created:	17 Dec 2025			

	umer	<b>S</b> Dasi	C Condition Guide	Created:	17 Dec 2025			
Make:	lake: Ford Model: Transit			Requires OK Attention			N/A	
Body Style:	Minibus	Year:	2004	Engine		OK	Attention	IN/A
Rego No.:	CBG829	Rego Expiry:	05 Jan 2027	Oil level		·		
WoF Expiry: 06 Aug 2026		Odometer:	71,509 Kms	Smoke & fumes		<i>'</i>		
Good No.:	27828618	VIN:	WF0EXXGBFE4B89353	Engine performance		·		
Next Service:	no sticker	Service History:	No	Noise		1		
lote: This report is	not a warranty	Coolant condition		1				
his report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or liagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling performance			
					Radiator / Hoses (visual)			
ey		Radiator / Hoses (visual)  Transmission						
	= Rust $C = C$ $\Gamma$ = Paint defect $P = P$	Operation 🗸						
- Dent 11	- Tallit delect 1 = 1	in dent SC = Stor	Noise		<i>'</i>			
s)(		Clutch		<i>'</i>				
		CV joints		<b>'</b>				
	$\sim$	Wheel bearings		<b>1</b>				
R PT W		<u> </u>	Brakes					
M	ID TO	Performan	CO.	·	Ι			
1				Hand brake		<i>'</i>		
DT CC W	6 I		Tyres (lowest observed tread depth of tyres)					
PT SC W				Left front 5.0 mn				
					Right front 5.0 m			
				Left rear 5.0 mi				
S		S D D		Right rear 6.0 mi				
				Spare Yes				
	and blemishes may not be	displayed in the diagra	ım	Suspensio	ın.	163		
Body Inspection  Both drip rails h				-		·	I	
Both front whee	el arch panels are rust	у		-	n performance erformance	<i>'</i>		
-	housing cracked			Shock abso		<i>'</i>		
	ing trim misaligned		Dry					
	ring Body Inspection	lman a stian Canan			ioning / Heater	·	Ι	l
Under Carriag  Underbody Ttre	e and Under Bonnet	inspection Comm	Operation	'Accessories				
	requires further inves	tigation				·	Ι	l
				Head lights	5	<b>, ,</b>	<b>V</b>	
				Tail lights			, v	
Interior Comm				Indicators	Language Parket	<i>V</i>		
Seats:	Good			Dashboard warning lights				
Carpets:	Good			Wipers (front & rear)				
Panels:	Good			Window winder FL		<i>'</i>		
Dashboard: Good					inder FR	•		<u> </u>
General Comn			Window w				<i>\</i>	
Both reverse lig Minor rust in do	hts not working or hinges			Window w				<b>'</b>
	J			Rear view r		•		
		T_	<del>.</del>	Radio (basi		<b>/</b>		
	ns During Test Drive	Dry	CD (basic test only)			<u> </u>		
Engine Timing		Unknown	Number of keys 3					
Evidence of Cam Belt Replacement Yes No Kms					king	•		<u> </u>
Inspected by:	Sione Mae			Remote loc	king	<b>/</b>		

I have read and understood this condition guide:

Inspection Date: 04 Dec 2025

Neil Honeyman

Published by:

NAME \_\_\_\_

SIGNATURE

Sat. nav. (basic test only)

Reversing camera