

Report ID:	27,828,723	Version:	3
Created:	02 Dec 2025		

Make:	Hyundai	Model:	loniq
Body Style:	Hatchback	Year:	2019
Rego No.:	MHG863	Rego Expiry:	30 Jul 2026
WoF Expiry:	31 Jul 2026	Odometer:	24,550 Kms
Good No.:	27828723	VIN:	KMHC751HUKU051220
Next Service:	37,316	Service History:	Yes
diagnostic testing u	e only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a for an additional charge.
Key			
	C = Rust $C = C$		
D = Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips
			W
Body Inspecti	w and blemishes may not be ion Comments ge and misaligned	P displayed in the diagra	am
Conditions Du	ring Body Inspection		Dry
Under Carria	ge and Under Bonnet	Inspection Comm	nents
Underbody cov	er damage		
Interior Comr	ments		
Seats:	Good		
Carpets:	Good		_
Panels:	Good		
Dashboard:	Good		
General Com	ments		
Equipped with I	both domestic and cor	mmercial charging o	cable

		Requires	
	OK	Attention	N/A
Engine		<u> </u>	
Oil level			
Smoke & fumes			
Engine performance	/		
Noise	/		
Coolant condition			<b>/</b>
Cooling performance	/		
Radiator / Hoses (visual)	~		
Transmission			
Operation	/		
Noise	~		
Clutch			<b>/</b>
CV joints	~		
Wheel bearings	<b>'</b>		
Brakes			
Performance	~		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		3	3.0 mm
Right front		3	3.0 mm
Left rear			1.0 mm
Right rear			5.0 mm
Spare	N/A		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	1		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL			
Window winder FR	<b>V</b>		
Window winder RL	~	-	
Window winder RR			
Rear view mirrors	· ·		
	<i>'</i>		
Radio (basic test only)		-	
CD (basic test only)	2	<u> </u>	
Number of keys	2	1	<u> </u>
Central locking	<i>V</i>		
Remote locking	•		
Sat. nav. (basic test only)			
Reversing camera			

I have read and understood
this condition guide:

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 02 Dec 2025

Kilipati Mae

Kilipati Mae

NAME			

No

Unknown

Yes

SI	GN	AT	URF	

Kms