

•	Report ID:	27,828,982	Version:	1
	Created:	10 Dec 2025		

	1000	Rasi	c Condition Guide	Report ID:	27,828,982	Ve	rsion: 1	
	umer	<u> </u>		Created:	10 Dec 2025			
Make:	Honda	Model:	Stream			01/	Requires	
Body Style:	Wagon	Year:	2004	Ok		OK	Attention	N/A
Rego No.:	GZW310	Rego Expiry:	21 Aug 2026	Engine				1
WoF Expiry:	04 Nov 2026	Odometer:	225,966 Kms	Oil level			-	
Good No.:	27828982	VIN:	7AT08GADX13007353	Smoke & fumes			1	
Next Service:	240,000	Service History:	Yes	Engine performance			-	
Note: This report is not a warranty					n diti on	1		-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Coolant co		1		-
				Cooling pe		1		<u> </u>
ey					Hoses (visual)			
	$= Rust \qquad C = C$. J		Transmission			
= Dent P	$\Gamma = Paint defect P = P$	in dent SC = Stor	ne Chips	Operation		/		├
		S S		Noise		-		<u> </u>
				Clutch			-	'
				CV joints		/	-	├
sw /				Wheel bea	rings	/		<u> </u>
— A	18			Brakes				
					ce	/	-	<u> </u>
SPT				Hand brake	2	/		
				Tyres (lowest observed tread depth of tyres)				
				Left front				6.0 m
				Right front			-	7.0 m
				Left rear				4.0 m
S S				Right rear			;	3.0 m
ote: some defects	and blemishes may not be	displayed in the diagra	ım	Spare No				
Body Inspecti	on Comments			Suspensio	n			
		ne chips and dents	all over. Paintwork faded, clear	Suspension	n performance	/		
coating coming	off in areas			Steering pe	erformance	V		
				Shock abso	orbers	V		
Conditions During Body Inspection Dry				Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
Oil leaks				Electrical / Accessories				
				Head lights	5	V		
				Tail lights		1		
Interior Comments				Indicators		~		
Seats: Average			Dashboard	warning lights	/			
Carpets:	Average		-	Wipers (fro			~	
Panels:	Average			Window w		1		<u> </u>
Dashboard:	Average			Window w		1	†	
Pashboard. Nerage						ļ		

Interior Comments				
Seats:	Average			
Carpets:	Average			
Panels:	Average			
Dashboard:	Average			
General Comments				

Air conditioning knob missing, functional and heating ok along with reverse camera. Rear washer nw. Mirrors don't retract, driver doesn't adjust. Radio doesn't work

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Car	Evidence of Cam Belt Replacement		No	224,398 Kms
Inspected by:	Gary Adams			
Published by:	Saxon Ewen			
Inspection Date:	05 Dec 2025			

I have read and understood		
this condition guide:	NAME	SIGNATURE

Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only) CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1

2

1 1