

Basic Condition Guide

Report ID:	27,829,505	Version:	2
Created:	23 Dec 2025		

	Great Wall	Model:	Steed
Body Style:	Utility	Year:	2020
Rego No.:	NDY140	Rego Expiry:	09 Feb 2026
WoF Expiry:	20 Dec 2026	Odometer:	116,690 Kms
Good No.:	27829505	VIN:	LGWCB3186LB630182
Next Service:	126000kms	Service History:	No
iagnostic testing un	only. Consideration is made	een driven up to 50km/h	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.
Yey			,
= Scratch R =	= Rust $C = C$	rack *= Deca	ls W = Significant scuffs
D = Dent PT	= Paint defect $P = P$	in dent SC = Stor	ne Chips
		PP	W
	(D)=		PT P
sc w			
$ \beta$	Man N		HIV
74			
D			
			S
	S	SC	SP
	and blemishes may not be	displayed in the diagra	m
Note: some defects a Body Inspection Missing tie down	on Comments		
Body Inspection			
Body Inspection	on Comments		
Body Inspection Missing tie down	on Comments on ropes on tray cover		Dry
Body Inspection Missing tie down Conditions Duri	on Comments In ropes on tray cover	Inspection Comm	Dry
Body Inspection Missing tie down Conditions Duri	on Comments In ropes on tray cover Ing Body Inspection E and Under Bonnet	Inspection Comm	-
Body Inspection Missing tie down Conditions Duri Under Carriage Rust rear bumpe	on Comments In ropes on tray cover Ing Body Inspection e and Under Bonnet	Inspection Comm	-
Body Inspection Missing tie down Conditions Duri Under Carriage Rust rear bumpe	on Comments In ropes on tray cover Ing Body Inspection e and Under Bonnet	Inspection Comm	-
Body Inspection Missing tie down Conditions Duri Under Carriage Rust rear bumpe	ing Body Inspection e and Under Bonnet er y engine cover	Inspection Comm	-
Body Inspection Missing tie down Conditions Duri Under Carriage Rust rear bumpe Rusty underbody	ing Body Inspection e and Under Bonnet er y engine cover	Inspection Comm	-
Body Inspection Missing tie down Conditions Duri Under Carriage Rust rear bumpe Rusty underbody	ing Body Inspection e and Under Bonnet er y engine cover	Inspection Comm	-
Conditions Duri Under Carriage Rust rear bumpe Rusty underbody	ing Body Inspection e and Under Bonnet er y engine cover	Inspection Comm	-
Conditions During Under Carriage Rust rear bumper Rusty underbody Interior Communications Carpets:	ing Body Inspection e and Under Bonnet er y engine cover Good Good	Inspection Comm	-
Conditions Duri Under Carriage Rust rear bumpe Rusty underbode Interior Comm Seats: Carpets: Panels:	ing Body Inspection e and Under Bonnet er y engine cover Good Good Good Good	Inspection Comm	-
Conditions Duri Under Carriage Rust rear bumpe Rusty underbode Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	ing Body Inspection e and Under Bonnet er y engine cover Good Good Good Good Good Good Good Go	Inspection Comm	-
Conditions Duri Under Carriage Rust rear bumpe Rusty underbody Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	ing Body Inspection e and Under Bonnet er y engine cover Good Good Good Good Good Hents not operating th displayed		-
Conditions Duri Under Carriage Rust rear bumpe Rusty underbody Interior Comm Seats: Carpets: Panels: Dashboard: General Comm Drivers window of the pressure lige Road Condition	ing Body Inspection e and Under Bonnet er y engine cover Good Good Good Good Good hents not operating th displayed as During Test Drive	Dry	-
Conditions Duri Under Carriage Rust rear bumpe Rusty underbode Interior Comm Seats: Carpets: Panels: Dashboard: General Comm Drivers window of the pressure lig Road Condition Engine Timing of	ing Body Inspection e and Under Bonnet er y engine cover Good Good Good Good Good hents not operating th displayed as During Test Drive		-

	OK	Requires Attention	
Engine	OIL	Accention	14//1
Oil level	V		
Smoke & fumes	V		
Engine performance	/		
Noise			
Coolant condition	V V		
Cooling performance	<i>'</i>		
Radiator / Hoses (visual)	<i>-</i>		
Transmission			
Operation	J	I	
Noise	·		
Clutch	·		
	-/		
CV joints	<i>V</i>		
Wheel bearings			
Brakes		I	
Performance	/		
Hand brake			
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7 mm
Right front			7 mm
Left rear			7 mm
Right rear			7 mm
Spare	Yes		
Suspension		ı	
Suspension performance	✓		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation		/	
Electrical / Accessories			
Head lights	/		
Tail lights	✓		
Indicators	<i>y y</i>		
Dashboard warning lights			
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR		~	
Window winder RL	1		
Window winder RR	V		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	1		
Central locking	/	1	
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera			V
J			

I have read and understood this condition guide:

Inspection Date: 04 Dec 2025

Published by:

Neil Honeyman

NAME

SIGNATURE