

## **Basic Condition Guide**

Report ID:	27,830,296	Version:	2
Created:	08 Dec 2025		

U	nuel	S Bas	ic Condition Guide	Created: 08 Dec 2		
Make:	Toyota	Model:	Hilux			
Body Style:	Utility	Year:	2018	Engine		
Rego No.:	LSQ22	Rego Expiry:	08 Jan 2026	Oil level		
WoF Expiry:	12 Feb 2026	Odometer:	145,251 Kms	Smoke & fumes		
Good No.:	27830296	VIN:	MR0JA3DD000344686			
Next Service:		Service History:	No	Engine performance		
Note: This report is	s not a warranty			Noise		
This report is a guid	e only. Consideration is made	e for age and mileage. P	arts have not been dismantled or 'h from cold. The Vendor recommends a	Coolant condition		
full mechanical insp	pection prior to purchase an	d this can be arranged	for an additional charge.	Cooling performance		
Key				Radiator / Hoses (visua		
	R = Rust $C = C$		3	Transmission		
D = Dent P	PT = Paint defect P = P	in dent SC = Sto	one Chips	Operation		
SC		S	W	Noise		
$\overline{}$				Clutch		
				CV joints		
SC W				Wheel bearings		
	18			Brakes		
		$\mathbb{N}$		Performance		
				Hand brake		
				Tyres (lowest observe		
				Left front		
			Р	Right front		
	-	S	W	Left rear		
PT	Right rear					
Note: some defects	lote: some defects and blemishes may not be displayed in the diagram					
<b>Body Inspect</b>	ion Comments			Suspension		
				Suspension performar		
				Steering performance		
				Shock absorbers		
Conditions Du	iring Body Inspection			Air Conditioning / He		
Under Carria	ge and Under Bonnet	Inspection Comn	nents	Operation		
				Electrical / Accessorie		
				Head lights		
				Tail lights		
Interior Com	ments			Indicators		
Seats:	Good			Dashboard warning lig		
Carpets:	Good			Wipers (front & rear)		
Panels:	Good			Window winder FL		
Dashboard:	Good			Window winder FR		
General Com				Window winder RL		
Missing cover of	Window winder RR					
J (	Rear view mirrors					
				Radio (basic test only)		
Pood Condition	une During Test Drive	Dry				
Road Conditio	ns During Test Drive	Dry		CD (basic test only)		

	011	Requires					
Fundam	OK	Attention	N/A				
Engine							
Oil level	<i>'</i>						
Smoke & fumes							
Engine performance	\( \times \)						
Noise							
Coolant condition							
Cooling performance							
Radiator / Hoses (visual)	~						
Transmission		Γ					
Operation	· ·						
Noise	<i>'</i>						
Clutch							
CV joints							
Wheel bearings		<u> </u>					
Brakes		I					
Performance							
Hand brake							
Tyres (lowest observed tread de	epth of						
Left front			9.0 mm				
Right front			9.0 mm				
Left rear			9.0 mm				
Right rear			9.0 mm				
Spare	Yes						
Suspension							
Suspension performance	<i>'</i>						
Steering performance	/						
Shock absorbers							
Air Conditioning / Heater		T					
Operation							
Electrical / Accessories		1					
Head lights	<b>/</b>						
Tail lights	<b>/</b>						
Indicators	<b>/</b>						
Dashboard warning lights	<b>✓</b>						
Wipers (front & rear)	V V V						
Window winder FL							
Window winder FR	V V						
Window winder RL							
Window winder RR	/						
Rear view mirrors	/						
Radio (basic test only)	/						
CD (basic test only)			<b>V</b>				
Number of keys	3						
Central locking	/						
Remote locking	/						
Sat. nav. (basic test only)			~				
Reversing camera	<b>/</b>						

I have read and understood this condition guide:

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 03 Dec 2025

Nigel Ikitule

Gino Petri

NAME

Timing Chain

No

Yes

SIGNATURE

Kms