

Report ID:	27,830,573	Version:	1
Created:	09 Dec 2025		

	nue	S Basi	c Condition Guide
Make:	BMW	Model:	Х3
Body Style:	SUV	Year:	2015
Rego No.:	JMH57	Rego Expiry:	01 Apr 2026
WoF Expiry:	24 Mar 2026	Odometer:	114,302 Kms
Good No.:	27830573	VIN:	WBAWZ520700P81896
Next Service:	130,000	Service History:	Yes
nis report is a guid agnostic testing u		een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends or an additional charge.
Key			
	R = Rust $C = CPT = Paint defect$ $P = Paint defect$		W = Significant scu
	. raine defect i = Ii		
		S	
S SC			
	119/1		
		-	
S SC	118		
	THE ST		
/			(Q)
		S S	
te: some defect	s and blemishes may not be	displayed in the diagra	am
	ion Comments		
mergency tire	e inflation device is in t	he boot	
Conditions Du	uring Body Inspection		Dry
	ge and Under Bonnet	Inspection Comm	-
Interior Com	ments		
Seats:	Average		
	_ ·		

		Requires	
Engine	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	V		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)			
Transmission	1	1	
Operation	/		
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread o	lepth of	tyres)	
Left front		5	5.0 mm
Right front		5	5.0 mm
Left rear		4	1.0 mm
Right rear			1.0 mm
Spare	N/A		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories		<u> </u>	
Head lights	/		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	~		
Window winder RL	· /		
Window winder RR	1		
Rear view mirrors	· /		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	1	<u> </u>	Ь
	· /	1	<u> </u>
Central locking	1		
Remote locking	V		
Sat. nav. (basic test only)	.,		
Reversing camera			1

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Air conditioning and heating systems along with reverse camera and navigation working

		<u></u>
Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Laura Iovine	
Inspection Date:	05 Dec 2025	

have read and understood
his condition quide

NAME			

SI	GN	AT	URF	