

Basic Condition Guida

| • | Report ID: | 27,831,910 | Version: | 1 |
|---|------------|-------------|----------|---|
| | Created: | 04 Dec 2025 | | |

| Basic Condition Guide | | | Created: 04 Dec 2025 | | | | | |
|--|----------------------------|---------------------------|----------------------|--|----------------|---------------------------------------|----------|-------|
| | | | | Created: | 04 Dec 2025 | | | |
| Make: | Hyundai | Model: | Santa FE | | | 01/ | Requires | |
| Body Style: | SUV | Year: | 2008 | OK Attention | | N/A | | |
| Rego No.: | ELT937 | Rego Expiry: | 04 Feb 2026 | Engine Oil level | | V | | 1 |
| WoF Expiry: | 09 Apr 2026 | Odometer: | 251,595 Kms | Smoke & fu | | <i>'</i> | | +- |
| Good No.: | 27831910 | VIN: | KMHSH81WR8U371543 | | | - | | + |
| Next Service: | 254,250 Kms | Service History: | No | Engine performance | | | + | |
| Note: This report is not a warranty | | | | Noise Coolant co | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | - |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a | | | | | | V | | ┼ |
| full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | erformance | - | | - |
| Key | | | | | Hoses (visual) | / | | |
| | | Crack *= Deca | 3 | Transmiss | ion | | T | Т |
|) = Dent P | PT = Paint defect P = P | Pin dent SC = Sto | ne Chips | Operation | | V | | ┼ |
| SP | | PSP | S | Noise | | V | | ļ , |
| | | \top | | Clutch | | | | ' |
| | | | SP | CV joints | | / | | |
| S PT / | | | | Wheel bea | rings | / | | |
| - P | 18 | | | Brakes | | | | |
| | M = 1 | | | Performan | ce | ~ | ļ | |
| | | | | Hand brake | | | | |
| s | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| S | | | | Left front | | | | 1.3 m |
| | | | | Right front | : | | | 1.5 m |
| | - | | | Left rear | | 3.9 | | 3.9 m |
| S P S SD | | | | Right rear | | 6.3 | | 6.3 m |
| lote: some defects | s and blemishes may not be | e displayed in the diagra | am | Spare | | Yes | | |
| Body Inspect | ion Comments | | | Suspensio | n | | | |
| Right wing mir | | | | Suspension | n performance | / | | |
| Boot trim loose |). | | | Steering po | erformance | ~ | | |
| | | | | Shock abso | orbers | / | | |
| Conditions Du | iring Body Inspection | | Dry | Air Conditioning / Heater | | | | |
| Under Carriage and Under Bonnet Inspection Comments | | | Operation | | ~ | | | |
| Oil leak. | | | | Electrical / Accessories | | | | |
| Left Tie rod grease build up. | | | | Head light: | S | / | | Τ |
| | | | | Tail lights | | 1 | | |
| Interior Comments | | | | Indicators | | 1 | | |
| Seats: Average | | | Dashboard | l warning lights | 1 | | | |
| Carpets: | Average | | | Wipers (fro | | 1 | | |
| Panels: | Average | | | Window w | | 1 | | |
| Dashboard: | Average | | | Window w | | 1 | | 1 |
| | J - | | | | | | + | + |

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|-------------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Kees Gould | |
| Published by: | Nitiphum Yordsiri | |
| Inspection Date: | 04 Dec 2025 | |

| have read and understood |
|--------------------------|
| his condition quide |

General Comments

| NAME | | | |
|------|--|--|--|

| NATURE | | |
|--------|--|--|

1

1

1

1

1

1

Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera