

•	Report ID:	27,833,795	Version:	3
	Created:	17 Dec 2025		

Elgrand		ОК	Requires Attention	N/A	
2005	Engine				
22 Jan 2026	Oil level	1			
63,889 Kms	Smoke & fumes	1			
7AT0DH6MX17012878	Engine performance	1			
10	Noise	1			
have and have Proved day	Coolant condition	1			
have not been dismantled or om cold. The Vendor recommends a	Cooling performance	1			
nn additional charge.	Radiator / Hoses (visual)	1			
W = Significant scuffs	Transmission				
Chips	Operation	V			
	Noise	1			
S SC	Clutch			_	
	CV joints	1			
SPT	Wheel bearings	1			
	Brakes		<u> </u>		
	Performance	V			
PT SC	Hand brake	1			
	Tyres (lowest observed tread depth of tyres)				
	Left front	deptiroi		l.5 mn	
SC	Right front			l.5 mn	
	Left rear			2.0 mn	
D SC	Right rear			2.5 mn	
	Spare	Yes			
	Suspension	100			
	Suspension performance	V			
	Steering performance	-			
	Shock absorbers	· ·			
Vet	Air Conditioning / Heater				
		V			
its	Operation Characterists				
	Electrical / Accessories	V	1		
	Head lights	V			
	Tail lights Indicators	1			
	Dashboard warning lights	1			
	Wipers (front & rear)	1			
	Window winder FL	/			
	Window winder FR	-			
	Window winder RL			•	
	Window winder RR				
	Rear view mirrors	-			
	Radio (basic test only)		<b>/</b>		
	CD (basic test only)				
	Number of keys	2			
No Kms	Number of keys Central locking	2			
No Kms	•				

Make:	Nissan	Model:	Elgrand					
Body Style:	Van	Year:	2005					
Rego No.:	LCR113	Rego Expiry:	22 Jan 2026					
WoF Expiry:	19 Mar 2026	Odometer:	163,889 Kms					
Good No.:	27833795	VIN:	7AT0DH6MX17012878					
Next Service:	174,000 Kms	Service History:	No					
Note: This report is r This report is a guide of diagnostic testing und	not a warranty only. Consideration is made	e for age and mileage. Pa een driven up to 50km/h	orts have not been dismantled or					
	= Rust C = Cl = Paint defect P = Pi							
S SC Note: some defects a	P and blemishes may not be	SC D SC	SC D SC					
Body Inspection		aispiayea iii aile alagia						
LH mirror lens b	roken.							
Conditions Duri	ng Body Inspection		Wet					
Engine oil leak. Minor underbody	e and Under Bonnet  / surface rust.	Inspection Comm	ents					
Interior Comm	ents							
Seats:	Average, RF seat							
Carpets:	Good							
Panels: Average								
Dashboard: Average								
General Comments								
CD player not ta Radio controls fa	king disc. ail but works from stee	ering wheel controls	S.					
Road Condition	s During Test Drive	Dry						
Engine Timing Mechanism		Timing Chain						

I have read and understood	k
this condition guide:	

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 12 Dec 2025

Caleb Spicer Lee

Shanna Bullion

Reversing camera