

Report ID:	27,833,851	Version:	2
Created:	24 Dec 2025		

Make:	Mazda	Model:	Atenza	
Body Style:	Sedan	Year:	2012	
Rego No.: PRY426		Rego Expiry:	08 Jul 2026	
WoF Expiry:	01 Jan 2027	Odometer:	76,218 Kms	
Good No.:	27833851	VIN:	7AT0C139X22100528	
Next Service:	85,000 kms	Service History:	No	
liagnostic testing ur ull mechanical insp	not a warranty	de for age and mileage. Pa been driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.	
	= Rust $C = 0$ T = Paint defect $P = 1$	Crack *= Deca Pin dent SC = Sto		
S)		S S	W S	
	(O)=		SD	
SD		<u> </u>		
- P	MATI		THE PARTY OF THE P	
			SC	
	10< 11.			
S				
			S	
S	W	SS	WS	
Intersome defects	and blemishes may not b	e displayed in the diagra	ım	
Body Inspecti				
Body Inspecti				
Body Inspecti Tyre mobility ki	t available		Dny	
Body Inspecti Tyre mobility ki Conditions Du	t available ring Body Inspection	t Inspection Comm	Dry	
Body Inspecti Tyre mobility ki Conditions Du Under Carriag	t available	t Inspection Comm		
Body Inspecti Tyre mobility ki Conditions Du Under Carriag	t available ring Body Inspection	t Inspection Comm		
Body Inspecti Tyre mobility ki Conditions Du	t available ring Body Inspection	t Inspection Comm		
Body Inspecti Tyre mobility ki Conditions Du Under Carriag	t available ring Body Inspection ge and Under Bonne	t Inspection Comm		
Body Inspecti Tyre mobility ki Conditions Du Under Carriag Fwd Interior Comm	t available ring Body Inspection ge and Under Bonne nents	t Inspection Comm		
Body Inspecti Tyre mobility ki Conditions Du Under Carriag Fwd Interior Comm Seats:	ring Body Inspection ge and Under Bonne nents Good	t Inspection Comm		
Conditions Du Under Carriag Fwd Interior Comm Seats: Carpets:	ring Body Inspection ye and Under Bonne nents Good Good	t Inspection Comm		
Body Inspecti Tyre mobility ki Conditions Du Under Carriag Fwd Interior Comm Seats: Carpets: Panels:	ring Body Inspection ge and Under Bonne nents Good Good Good	t Inspection Comm		
Conditions Du Under Carriag Fwd Interior Comm Seats: Carpets: Panels: Dashboard:	ring Body Inspection ge and Under Bonne nents Good Good Good Good	t Inspection Comm		
Conditions Du Under Carriag Fwd Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	ring Body Inspection ge and Under Bonne nents Good Good Good Good Good ments	t Inspection Comm		
Conditions Du Under Carriag Fwd Interior Comm Seats: Carpets: Panels: Dashboard:	ring Body Inspection ge and Under Bonne nents Good Good Good Good Good ments	t Inspection Comm		

	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	/		
Engine performance	\(\times \) \(\t		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission		ı	
Operation	/		
Noise	/		
Clutch			
CV joints	_		
Wheel bearings	/		
Brakes	-	<u> </u>	
Performance	1		
Hand brake	<i>-</i>		
Tyres (lowest observed tread d	enth of	turas)	
Left front	Сригог		1.0 mm
Right front			1.0 mm
Left rear			7.0 mm
			7.0 mm
Right rear	N/A		.0 111111
Spare	IN/A		
Suspension		Ι	
Suspension performance	~		
Steering performance			
Shock absorbers	•		
Air Conditioning / Heater	J	I	
Operation	•		
Electrical / Accessories		<u> </u>	
Head lights	•		
Tail lights	•		
Indicators	/		
Dashboard warning lights	_	/	
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	1		
Window winder RL			
	/		
Window winder RR	<i>V</i>		
Window winder RR Rear view mirrors	/		
	<i>V</i>		
Rear view mirrors	V V		
Rear view mirrors Radio (basic test only)	V V		<i>'</i>
Rear view mirrors Radio (basic test only) CD (basic test only)	\(\sigma \)		<i>'</i>
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	\(\times \)		<i>'</i>
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\times \)		

have read and understood
this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 22 Dec 2025

Admond Chan

Engine Timing Mechanism

Inspected by:

Published by:

N	Λ	RΛ	Е	

Vasanthakumar Mayilswamy

Dry

Timing Chain

No

Yes

Kms