

| Report ID: | 27,834,183  | Version: | 2 |
|------------|-------------|----------|---|
| Created:   | 15 Dec 2025 |          |   |

Requires Attention

N/A

| CA T   | 11000                      | Rasi                      | ic Condition Guide   | Report ID: 27,834,183        |         |
|--|----------------------------|---------------------------|--|------------------------------|---------|
|  | ntue                       |                           |  | Created: 15 Dec 2025         |         |
| Make:  | BMW                        | Model:                    | 1301   |                              | Oł      |
| Body Style:  | Hatchback                  | Year:                     | 2005   | Fngine                       |         |
| Rego No.:  | RMZ365                     | Rego Expiry:              | 24 Oct 2026  | Engine                       |         |
| WoF Expiry:  | 02 Apr 2026                | Odometer:                 | 138,725 Kms  | Oil level                    |         |
| Good No.:  | 27834183                   | VIN:                      | WBAUF92040PS88577  | Smoke & fumes                |         |
| Next Service:  | 150000                     | Service History:          | No   | Engine performance           |         |
| Note: This report is   | not a warranty             | ,                         |  | Noise                        | •       |
| This report is a quide   | only. Consideration is mad | de for age and mileage. P | arts have not been dismantled or<br>h from cold. The Vendor recommends a | Coolant condition            | •       |
| ull mechanical insp  | ection prior to purchase a | nd this can be arranged f | for an additional charge.  | Cooling performance          | -       |
| Кеу  |                            |                           |  | Radiator / Hoses (visual)    | •       |
| S = Scratch R  | = Rust $C=0$               | Crack *= Deca             | lls W = Significant scuffs   | Transmission                 |         |
| D = Dent PT = Paint defect P = Pin dent SC = Stone Chips                   |                            |                           | Operation  | -                            |         |
|  | W                          | D                         |  | Noise                        | -       |
| $\overline{}$  | $\overline{}$              | $\top$                    |  | Clutch                       |         |
|  | \ \( \)                    |                           | SW   | CV joints                    | -       |
|  |                            |                           |  | Wheel bearings               |         |
| $-\!\!\!\!-\!$ |                            |                           |  | Brakes                       |         |
|  | IMP II                     |                           | PT   | Performance                  | -       |
|  |                            |                           |  | Hand brake                   | -       |
|  | 18                         |                           |  | Tyres (lowest observed tread | d depth |
|  |                            |                           |  | Left front                   |         |
|  |                            |                           | PT   | Right front                  |         |
|  |                            |                           |  | Left rear                    |         |
|  |                            | )[                        |  | Right rear                   |         |
| Note: some defects   | and blemishes may not b    | e displayed in the diagra | am   | Spare                        | N       |
| Body Inspecti  | on Comments                |                           |  | Suspension                   |         |
|  |                            |                           |  | Suspension performance       |         |
|  |                            |                           |  | Steering performance         | -       |
|  |                            |                           |  | Shock absorbers              | -       |
| Conditions Dur   | ring Body Inspection       |                           | Dry  | Air Conditioning / Heater    |         |
| Under Carriag  | ge and Under Bonne         | t Inspection Comm         | nents  | Operation                    | -       |
|  | s sump, rear main are      | •                         |  | Electrical / Accessories     |         |
| Surface rust on  | front shock bodies         |                           |  |                              |         |

| Interior Comments |         |  |
|-------------------|---------|--|
| Seats:            | Average |  |
| Carpets:          | Average |  |
| Panels:           | Average |  |
| Dashboard:        | Average |  |
| General Comments  |         |  |

Front suspension knock. Intermittent check engine light on.

| Road Condition   | s During Test Drive | Dry          |
|------------------|---------------------|--------------|
| Engine Timing I  | Mechanism           | Timing Chain |
| Evidence of Can  | n Belt Replacement  | Yes No Kms   |
| Inspected by:    | Greg Morgan         |              |
| Published by:    | Stuart Manson       |              |
| Inspection Date: | 03 Dec 2025         |              |

| have read and understood |      |           |  |
|--------------------------|------|-----------|--|
| his condition guide:     | NAME | SIGNATURE |  |

| Oli level                      |              |          |          |
|--------------------------------|--------------|----------|----------|
| Smoke & fumes                  | <b>/</b>     |          |          |
| Engine performance             | <b>/</b>     |          |          |
| Noise                          | \( \sigma \) |          |          |
| Coolant condition              | /            |          |          |
| Cooling performance            | <b>V</b>     |          |          |
| Radiator / Hoses (visual)      | <b>/</b>     |          |          |
| Transmission                   |              |          |          |
| Operation                      | /            |          |          |
| Noise                          | \( \tau \)   |          |          |
| Clutch                         | •            |          |          |
| CV joints                      | •            |          |          |
| Wheel bearings                 | <b>'</b>     |          |          |
| Brakes                         |              |          |          |
| Performance                    | •            |          |          |
| Hand brake                     | /            |          |          |
| Tyres (lowest observed tread d | epth of      | tyres)   |          |
| Left front                     |              |          | 4.0 mm   |
| Right front                    |              |          | 4.0 mm   |
| Left rear                      |              |          | 3.0 mm   |
| Right rear                     |              |          | 4.0 mm   |
| Spare                          | N/A          |          |          |
| Suspension                     |              |          |          |
| Suspension performance         |              | <b>'</b> |          |
| Steering performance           | 1            |          |          |
| Shock absorbers                | •            |          |          |
| Air Conditioning / Heater      |              |          |          |
| Operation                      | <b>'</b>     |          |          |
| Electrical / Accessories       |              |          |          |
| Head lights                    | •            |          |          |
| Tail lights                    | ~            |          |          |
| Indicators                     | ~            |          |          |
| Dashboard warning lights       | ~            |          |          |
| Wipers (front & rear)          | •            |          |          |
| Window winder FL               | •            |          |          |
| Window winder FR               | ~            |          |          |
| Window winder RL               | ~            |          |          |
| Window winder RR               | •            |          |          |
| Rear view mirrors              | •            |          |          |
| Radio (basic test only)        | ~            |          |          |
| CD (basic test only)           |              |          |          |
| Number of keys                 | 1            |          |          |
| Central locking                | /            |          |          |
| Remote locking                 | •            |          |          |
| Sat. nav. (basic test only)    |              |          | <b>'</b> |
| Reversing camera               |              |          |          |
|                                |              |          |          |