

Basic Condition Guide

Report ID:	27,834,773	Version:	1
Created:	03 Dec 2025		

		ОК	Requires Attention	N/A
	Engine			
	Oil level	/		
	Smoke & fumes	/		
)W189043	Engine performance	/		
	Noise	/		
nantled or	Coolant condition	V		
r recommends a	Cooling performance	/		
.	Radiator / Hoses (visual)	/		
nificant scuffs	Transmission			
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Operation	/		
	Noise	1		
	Clutch			1
	CV joints	/		
D	Wheel bearings	1		
\/	Brakes			
	Performance	V	Ι	
PT	Hand brake	1		
	Tyres (lowest observed tread	depth of	tvres)	
<i>P</i>	Left front			3.6 mr
S	Right front			1.9 mr
	Left rear			3.7 mr
PT P	Right rear			1.0 mr
	Spare	Yes		
	Suspension	100		
		· /	I	
	Suspension performance Steering performance	· ·		
		V		
	Shock absorbers			
	Air Conditioning / Heater		l	Γ
	Operation	/		
	Electrical / Accessories		l	
	Head lights	/		
	Tail lights	/		
	Indicators	/		
	Dashboard warning lights	/		
	Wipers (front & rear)	/		
	Window winder FL	/		
	Window winder FR	/		
	Window winder RL	/		
	Window winder RR	/		
	Rear view mirrors	/		
	Radio (basic test only)	/		
	CD (basic test only)	/		
	Number of keys	1		
Kms	Central locking	/		
	Remote locking	/		
	Sat. nav. (basic test only)			1
	Reversing camera			1

Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2013
Rego No.: GZN88		Rego Expiry:	30 May 2025
WoF Expiry:	16 Jan 2026	Odometer:	212,756 Kms
Good No.:	27834773	VIN:	MNAUMFF50DW189043
Next Service:	220,000 Kms	Service History:	No
liagnostic testing ui	only. Consideration is made	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a for an additional charge.
(ey		,	
	= Rust $C = C$ T = Paint defect $P = P$		W = Significant scuffs ne Chips
	SD	PSCSDP	
	\sim $(0)_{\epsilon}$		
SSC			PT
			S
SDPT	S	S PT P	PT P
lote: some defects	and blemishes may not be	displayed in the diagra	am
Body Inspecti	on Comments		
Dents in rear of Right rear taillig			
Conditions Du	ring Body Inspection		Dry
Under Carriag	ge and Under Bonnet	Inspection Comn	nents
4WD Engine oil seep			
Interior Comm	nents		
Seats:	Average		
Carpets:	Average		
Panels:	Average		
Dashboard:	Average		
General Comi	ments		
Road Conditio	ns During Test Drive	Dry	
Engine Timing	Mechanism	Timing Chain	
Evidence of Ca	m Belt Replacement	Yes	No Kms

I have read and understood	k
this condition quide	

Inspection Date: 03 Dec 2025

Hoani Saunders

Malcolm Thomas

Inspected by:

Published by:

NAME			