

## **Basic Condition Guide**

Report ID:	27,834,938	Version:	1
Created:	04 Dec 2025		

	ntuei	S Bas	ic Condition Guide	Created: 04 Dec 2025				
Make:	Rover	Model:	75		OK	Requires	NI/A	
Body Style:	Sedan	Year:	2005	Engine	OK	Attention	N/A	
Rego No.:	CQW260	Rego Expiry:	02 May 2026	Oil level	· ·			
WoF Expiry:	27 Jan 2026	Odometer:	203,939 Kms	Smoke & fumes	1			
Good No.:	27834938	VIN:	SARRJSLLM5D341090	Engine performance	•			
Next Service:	212,000 Kms	Service History:	Yes	Noise	1			
ote: This report is	not a warranty			Coolant condition	1			
iagnostic testing ur	ndertaken. The vehicle has l	been driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling performance	1			
Il mechanical insp	ection prior to purchase ar	nd this can be arranged t	for an additional charge.	Radiator / Hoses (visual)	1			
ey		S * D	als W = Significant scuffs	Transmission				
	= Rust $C = 0$ T = Paint defect $P = P$	Crack	Operation	· /				
- Dent 1	T-Tunt defect T-1	mucht 5c-5to	The Crips	Noise	1			
s sc		SPSD	W P	Clutch			/	
				CV joints		<del> </del>		
	$\sim$		(O) SW	Wheel bearings	1			
S SC W				Brakes				
M	10 Th		All	Performance	V	1		
1			PT SC	Hand brake	1			
0.0.00	10 II					itumos)		
S D SC				Tyres (lowest observed tread  Left front	5.4 mm			
			Right front	4.6 mn				
W	w	PTP SP	Left rear	3.3 mm				
			Right rear	4.7 mm				
	and blemishes may not b	e displayed in the diagr	am	Spare	Yes			
* .	on Comments			Suspension		T		
•	secured in boot ront windscreen			Suspension performance	-			
				Steering performance	/			
			Dry	Shock absorbers	/			
	ring Body Inspection		Air Conditioning / Heater					
	e and Under Bonne	t Inspection Comn	Operation	/				
2WD Dil seep			Electrical / Accessories					
•	underside of vehicle		Head lights	/				
				Tail lights	/			
Interior Comn	nents			Indicators	/	ļ		
Seats:	Average			Dashboard warning lights	/			
Carpets:	Average			Wipers (front & rear)	/			
Panels:	Average		Window winder FL	/				
Dashboard:	Good		Window winder FR	/				
General Comr	ments		Window winder RL	<b>'</b>				
ngine misfire			Window winder RR	/				
Engine cover de nterior roof linir			Rear view mirrors	~				
	nistory invoices			Radio (basic test only)	1			
	ns During Test Drive	Dry		CD (basic test only)			1	
Engine Timing Mechanism Cambelt				Number of keys	1		<u> </u>	
				.,		,		

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 04 Dec 2025

Hoani Saunders

Malcolm Thomas

NAME

✓ Yes

No

SIGNATURE

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1

1

115,784 Kms