

## **Basic Condition Guide**

Report ID:	27,835,215	Version:	1
Created:	05 Dec 2025		

Make:	Honda	Model:	Vezel	
Body Style:	Wagon	Year:	2014	
Rego No.:	RAU404	Rego Expiry:	19 Jul 2025	
WoF Expiry:	03 Feb 2026	Odometer:	47,974 Kms	
Good No.:	27835215	VIN:	7AT08GDHX24047023	
Next Service:	57,831	Service History:	No	
diagnostic testing ui	only. Consideration is made	een driven up to 50km/h	rts have not been dismantled or from cold. The Vendor recommends a or an additional charge.	
Key				
	= Rust C = C			
D = Dent P	T = Paint defect P = P	in dent SC = Stor	ne Chips	
SC				
			$\overline{}$	
sc				
SC			PT SC	
		D	PT	
	and blemishes may not be on Comments	displayed in the diagra	m 	
body mspecu	on comments			
			Г	
Conditions Du	ring Body Inspection		Drv	
	ring Body Inspection	Inspection Comm	Dry	
	ring Body Inspection ge and Under Bonnet	Inspection Comm		
		Inspection Comm		
		Inspection Comm		
Under Carriag	ge and Under Bonnet	Inspection Comm		
Under Carriag	ge and Under Bonnet	Inspection Comm		
Interior Comm	nents Average	Inspection Comm		
Interior Communication Seats: Carpets:	nents Average Average	Inspection Comm		
Interior Comm Seats: Carpets: Panels:	nents Average Average Average Average	Inspection Comm		
Interior Communication Seats: Carpets: Panels: Dashboard:	nents Average Average Average Good	Inspection Comm		
Interior Common Seats: Carpets: Panels: Dashboard: General Common Seats	nents Average Average Average Good ments		ents	
Interior Common Seats: Carpets: Panels: Dashboard: General Common Seats	nents Average Average Average Good		ents	
Interior Common Seats: Carpets: Panels: Dashboard: General Common Tyre repair kit in	nents Average Average Average Good ments nstead of spare wheel		ents	
Interior Common Seats: Carpets: Panels: Dashboard: General Common Tyre repair kit in	nents Average Average Average Good ments nstead of spare wheel	. AC not blowing co	ents	

		Requires		
	OK	Attention	N/A	
Engine			ı —	
Oil level	~			
Smoke & fumes	/			
Engine performance	~			
Noise	•			
Coolant condition	•			
Cooling performance	~			
Radiator / Hoses (visual)	~			
Transmission		·		
Operation	~			
Noise	~			
Clutch			<b>V</b>	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand brake	<b>/</b>			
Tyres (lowest observed tread d	epth of	tyres)		
Left front			6 mm	
Right front			6 mm	
Left rear			6 mm	
Right rear			6 mm	
Spare	N/A			
Suspension				
Suspension performance	<b>/</b>			
Steering performance	/			
Shock absorbers	<b>/</b>			
Air Conditioning / Heater				
Operation		•		
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	V			
Dashboard warning lights	1			
Wipers (front & rear)	~			
Window winder FL				
Window winder FR	V			
Window winder RL	1			
Window winder RR	1			
Rear view mirrors	1			
Radio (basic test only)	1			
CD (basic test only)	1			
Number of keys	1			
Central locking	1			
Remote locking	1			
Sat. nav. (basic test only)				
Reversing camera	1			
<u></u>	<u> </u>			

I have read and understood
this condition guide:

Inspection Date: 05 Dec 2025

Inspected by:

Published by:

NAME	

Lewis Dolamore

Lewis Dolamore

S	IG	N	ΔT	ΓIJ	R	F