

Report ID: 27,835,386		Version:	2
Created:	31 Dec 2025		

U	nuel	S Basi	c Condition Guide
Make:	Subaru	Model:	Impreza
Body Style:	Hatchback	Year:	2008
Rego No.:	MNJ291	Rego Expiry:	16 Dec 2025
WoF Expiry:	06 Jan 2027	Odometer:	170,127 Kms
Good No.:	27835386	VIN:	7AT0GF09X19006146
Next Service:	180150	Service History:	No
diagnostic testing unfull mechanical inspo Key S = Scratch R	only. Consideration is made	een driven up to 50km/l d this can be arranged for track *= Deca	ls W = Significant scuffs
SC		S SC S SC	S SC S SC
S SC SC			sc
sc		SC P	
Note: some defects	and blemishes may not be	displayed in the diagra	m
Body Inspecti	_		
Minor stonechip	s on windscreen		
Conditions Dur	ing Body Inspection		Dry
Under Carriag	e and Under Bonnet	Inspection Comm	ents
All wheel drive			
Interior Comm	nents		
Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		
General Comr	nents		

		Requires	
Engino	OK	Attention	N/A
Engine Oil level	<b>/</b>		1
Smoke & fumes	<i>V</i>		
	./		
Engine performance	~		
Noise Coolant condition	· ·		
	<i>'</i>		
Cooling performance	•		
Radiator / Hoses (visual)  Transmission			
	•/	l	
Operation Noise	./		
Clutch	•		
	\( \sigma \)		
CV joints Wheel bearings	·/		
Brakes		l	
Performance	•/	I	
Hand brake	•		
Tyres (lowest observed tread d	anth of	turos)	
Left front	еритог	•	5.0 mm
Right front  Left rear			
Right rear Spare	Yes	-	5.5 mm
Suspension	163		
Suspension performance	1	I	Π
Steering performance	<i>y</i>		
Shock absorbers	<i>J</i>		
Air Conditioning / Heater			
Operation	<b>/</b>	I	
Electrical / Accessories			
Head lights	/	I	
Tail lights	·		
Indicators	<b>V</b>		
Dashboard warning lights	·		
Wipers (front & rear)	<b>V</b>		
Window winder FL	/	<del>                                     </del>	
Window winder FR	~		
Window winder RL	<b>✓</b>		
Window winder RR	<b>V</b>		
Rear view mirrors	<b>V</b>		
Radio (basic test only)	· ·		
CD (basic test only)	V		<del>                                     </del>
Number of keys	1	1	ш
Central locking	<b>V</b>		1
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera			·
, , <u>J</u>		<u>.                                    </u>	

Inspection Date:	05 Dec 2025
I have read and ui this condition gui	
•	

Missing both rear floor mats

Engine Timing Mechanism

Inspected by:

Published by:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Dry Cambelt

Cameron Senior-Arnold

Jaykib Collins

Yes

NAME		

**✓** No

Kms

SIGNATURE		