


Make:	BMW	Model:	335i
Body Style:	Wagon	Year:	2007
Rego No.:	HMF697	Rego Expiry:	18 Feb 2026
WoF Expiry:	02 May 2026	Odometer:	179,012 Kms
Good No.:	27836095	VIN:	WBAVS72070FG43416
Next Service:	187,500 kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch      R = Rust      C = Crack      \* = Decals      W = Significant scuffs  
D = Dent      PT = Paint defect      P = Pin dent      SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Both rear and passenger step rubber torn, both wing mirror cover paint defect, engine oil leak,

Conditions During Body Inspection	Dry
-----------------------------------	-----

#### Under Carriage and Under Bonnet Inspection Comments

### Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Good

## General Comments

Driver seat worn,r rear door window faulty,r sun visor light not working,middle cap holder not open,front wiper blade worn,

Road Conditions During Test Drive	Dry				
Engine Timing Mechanism	Timing Chain				
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Kms
Inspected by:	Marlon Espena				
Published by:	Marlon Espena				
Inspection Date:	10 Dec 2025				

I have read and understood  
this condition guide:

**NAME**

Report ID:	27,836,095	Version:	1
Created:	10 Dec 2025		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		7 mm	
Right front		6 mm	
Left rear		7 mm	
Right rear		7 mm	
Spare	N/A		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR		✓	
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

**SIGNATURE**