

Basic Condition Guide

Report ID:	27,836,957	Version:	4
Created:	16 Dec 2025		

U	ntuet	S Bas	ic Condition Guide		
Make:	Toyota	Model:	Prius		
Body Style:	Hatchback	Year:	2009		
Rego No.: PWB216 WoF Expiry: 25 Dec 2026		Rego Expiry:	31 Mar 2026 167,213 Kms		
		Odometer:			
Good No.:	27836957	VIN:	7AT0H637X22135536		
Next Service:	172,000	Service History:	Yes		
iagnostic testing ur	only. Consideration is mad	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a for an additional charge. -		
	= Rust $C = C$ T = Paint defect $P = P$		w = Significant scuff		
PT		SD S	S SC W		
S PT SC					
s sc					
PT	$\overline{}$	SSS			
	and blemishes may not be on Comments	displayed in the diagra	am		
, ,	<u> </u>	leadlights faded. P	aint coming off in patches		
LOOKING WHOO!	nat noy in giovozoni i	ioddiigino iddod. i	and conting on an paterior		
Conditions Du	ring Body Inspection		Dry		
	je and Under Bonnet	Inspection Comm	-		
carriag	, and officer bornier				
Interior Comn	nents				
Seats:	Average				
Carpets: Average					
Panels:	Average				
Dashboard:	Average				
General Comr					
Mirrors don't ref					
Road Condition	ns During Test Drive	Dry			
Engine Timing		Timing Chain			

	OK	Requires Attention	
Engine	OK	Accention	14//1
Oil level	/		
Smoke & fumes	1		
Engine performance			
Noise	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Coolant condition	<i>-</i>		
Cooling performance	1		
Radiator / Hoses (visual)	<i>y</i>		
Transmission			
Operation	1	<u> </u>	
Noise	1		
Clutch			
CV joints	./		_
Wheel bearings	•		
Brakes		l	
Performance	.,,	<u> </u>	
Hand brake	.,		
Traine State		1	
Tyres (lowest observed tread d	epth of		
Left front			3.0 mm
Right front			3.0 mm
Left rear			6.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	/		
Electrical / Accessories		,	
Head lights	1		
Tail lights	1		
Indicators	/		
Dashboard warning lights			
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1		
Window winder RL	/		
Window winder RR	1		
Rear view mirrors		V	
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	1		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			~
Reversing camera	1		
-			

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 09 Dec 2025

Gary Adams

Luke Saunders

NAME

Yes

No

SIGNATURE

Kms